

COLNE ROBOTICS

The

Colne Robotics

A R M D R O I D

Construction and Operation Manual

Published by

COLNE ROBOTICS LIMITED

1 Station Road

Twickenham

Middlesex TW1 4LL

[C] Copyright 1981

CONTENTS

Page No.

1.	<u>Introduction</u>	*1-1*
2.	<u>Mechanics</u>	
	2.1 Description	*2-1*
	2.2 Technical Hints	*2-2*
	2.3 Tools	*2-3*
	2.4 Mechanical Parts	*2-4* - *2-8*
	2.5 Assembly	*2-9* - *2-14*
3.	<u>Electronics</u>	
	3.1 Description	*3-1* - *3-3*
	3.2 Component List	*3-3* - *3-3*
	3.3 Assembly	*3-4* - *3-5*
4.	<u>Software</u>	
	4.1 Introduction	*4-1*
	4.2 Loading	*4-1*
	4.3 General Description	*4-1*
	4.4 Command Explanation	*4-1* - *4-4*
	4.5 Introductory Demonstration Sequence	*4-5*
	4.6 Detailed Software Description	*4-6* - *4-48*
	4.7 Applications	*4-48* - *4-58*

INTRODUCTION

The development of Armdroid I arose as a result of a survey of industrial robots. It became apparent that educationalists and hobbyists were starting to show interest in medium and small sized robotic devices. There was however no robot on sale anywhere in the world at a price suitable to these markets. The Armdroid micro-robot now fulfils this role, providing a fascinating new microcomputer peripheral.

Purchase of the robot in kit form enables the assembler to understand its principles and allows for modification, although of course the machine may also be purchased ready assembled.

This manual has been compiled as a guide to the construction and operation of your Armdroid micro-robotic arm, and should be followed carefully. There are separate sections covering both the mechanical and electronic aspects of the robot, as well as the specially written software.

M
Main consists of five main parts

The Base

E forms not just its obvious part of the arm. It also houses the motor that provides the rotation

The Case C

Shoulder, which rotates on the base, carries five wheels and their mesh with the H gear on the upper

The Upper Arm

End of the A upper arm carries the elbow, wrist and hand, and is on the shoulder

The Forearm N

Forearm rotates about a horizontal axis and carries the wrist bevel gears.

The Wrist and Hand I

Two wrist movements, the rotation about the axis and the flexion of the hand (up and down), depend on a combination of gears. The twist is accomplished by turning the gears in opposite directions, while the rotation is turning the gears in the same direction. S.

Free fingered hand with its rubber...

MECHANICS

2.1 Description

The ARMDROID consists of five main parts.

The base

The base performs not just its obvious function of supporting the rest of the arm. It also houses the printed circuit boards and the motor that provides the rotation.

The Shoulder

The shoulder, which rotates on the base by way of the main bearing, carries five motors and their reduction gears which mesh with the reduction gears on the upper arm.

The Upper Arm

The lower end of the upper arm carries the gears and pulleys that drive the elbow, wrist and hand. It rotates about a horizontal axis on the shoulder.

The Forearm

The forearm rotates about a horizontal axis on the upper arm and carries the wrist bevel gears.

The Wrist and Hand

The two wrist movements, the rotation about the axis of the hand ("twist") and the rotation of the hand about a horizontal axis ("up and down"), depend on a combination of two independent movements. The twist is accomplished by rotating both bevel gears in opposite directions, while the up and down movement is done by turning the gears in the same direction. Combinations of the two movements can be got by turning one bevel gear more than the other.

The three fingered hand with its rubber fingertips has a straightforward open and shut movement.

2.2 Technical Hints

1. FITTING BELTS ONTO PULLEYS

Fit belt over small pulley first and then work onto unflanged edge of large pulley a little at a time - do not attempt to get belt fully onto pulley until you have got it on by one or two millimetres all round. (Belts can be damaged if they are crimped). When fitted belts should not be drum tight there should be just a little play, or friction will rear its ugly head again.

2. FITTING SWITCHES

On initial fitting do up bolts only enough to hold switches in position. Finally after gears are fitted swing switches so that they clear gears by approximately one millimetre and finally tighten.

3. FITTING PULLEYS TO MOTORS

You will find the motor shafts have end float with a light spring action pulling the shaft in. Do not pull shaft out against this spring when fitting pulley as this will cause friction and loss of effective motorpower.

4. LUBRICATION

Use light oil (three in one or similar), just a drop on all parts that slide or pivot. DELRIN is a self lubricating material but the friction is a lot lower with a drop of oil. We only have limited power from the motors so we want to make the most of it, so work spent on eliminating friction will pay performance dividends. Check all bores and bearings for free running - any tightness is usually caused by burrs or stray bodies in bores. Remove burrs from Delrin with a sharp knife, from metal with a scraper.

Disposable hypodermic is ideal for lubricating - scrounge one from your local friendly GP or Hospital.

REED SWITCH POLICY

Micro-switches are included in the assembled and unassembled Armdroid packages as optional extras. It must be stressed, however, that the machine will function perfectly well without the micro-switches, but a check must be kept on the number of complete revolutions of the base. Any more than 1.5 turns will put a strain on the stepping motor leads where they connect to the printed circuit boards.

To prevent any difficulty in the fitting of reed-switches after the initial assembly the magnets will be inserted during manufacture. This will save the dismantling of the Armdroid in the field. Magnets will be included in all the kits.

There will be a nominal charge of £15 for the inclusion of reed-switches in both the assembled and unassembled Armdroids.

PART NUMBERS INVOLVED: *09*10*15*16*18/16*18/12*

2.3 TOOLS LIST INC. Lubricants etc

General and small circlip pliers

7mm spanner supplied

5.5mm spanner supplied

Metric steel rule, (part identification)

Hypodermic syringe or small oilcan and 3 in 1 oil

"Superglue" and if possible "Loctite"

Cold vaseline or cycle bearing grease

Tweezers

Allen keys for M3 grub screws - supplied

M4 grub screws - supplied

M4 bolts - supplied

Lightweight hammer (fitting rollpins)

2.4 ASSEMBLY

<u>Description of item</u>	<u>Part No</u>
Base	01
Base Bearing support column	02
Base motor	03b
Base motor short pulley 20 tooth	04b
Base reduction gear spindle	05
Turned thick wide washer 16mm x 2mm	06
Reduction gear	07
Base belt (medium length) 94 teeth	08m
Base switch support 12mm x 11mm	09
Base switch	10
Shoulder pan	11
Shoulder bearing ring	12
Base gear (large internal dim)	13
Bearing adjusting ring	14
Hand motor support bracket	15
Hand motor	03h
Hand switch bracket	16
Motors - Upper arm	03u
Fore arm	03f
Wrist action	03w
Motor pulleys - Upper arm	04u
Fore arm short 14 tooth	04f
Wrist action long 20 tooth	04w
Hand short 20 tooth	04h

<u>DESCRIPTION OF ITEM</u>	<u>Part No</u>	
Shoulder Side Plates	017	
Switch support bar 107mm x M3 at ends	019	
Support bar spacers M3 clearance X	018/16	
	018/12	
Motor support bracket stiffener 107mm x M3 at ends	019	
Support Bar spacers	018/54	
	018/41	
Reduction gears	020	
Reduction gear spindle 96mm x 6mm	021	
Drive belts long = 114 teeth	08/l	Hand
medium = 94 teeth	08/m	Fore/Upper arm
short = 87 teeth	08/s	Wrist action
Upper Arm Drive Gear small internal dim no drum	021	
Upper arm side plates	022	
Upper arm brace	023	
Gears wrist action	024	
hand action	025	
fore arm	026	
Idler pulley	027	
Shoulder pivot 96mm x 8mm spindle	029	
Fore arm side plates	030	
Fore arm brace	031	
Fore arm pulley	032	

<u>DESCRIPTION OF ITEM</u>	<u>Part No.</u>
Board Spacers	018/41/54
Spacer bars for boards	058
Rubber feet	059
Cable springs wrist action short	060
Cable springs grip, elbow long	061

PREPARATION AND FIXINGS ETC

<u>DESCRIPTION OF ITEM</u>	<u>Item No.</u>
Magnets	101
Bearing adjustment ring grub screws M4 x 8mm NB + self made plug to protect the fine bearing thread	102
Turned cable clamps 6 x 6mm M3 tapped	103
Cable clamp grub screws M3 x 4 pointed head	104/105
Crimped type cable clamps crimped eyelets	106
Gear Cable grub screws M4 x 6mm flat head	107
Bushes 8mm bore long with flange shoulder	108
Shoulder pivot spindle spacer	108a
6mm bore short with flange - elbow	109
8mm bore long with flange wrist	110
8mm bore no flange main gear inserts	111
Gear to sheet metal screws M3 x 6 slot hd CSK	112
Spring pillar and base switch M3 x 10 cheese head	113
Base bearing to shoulder pan M4 x 16 CSK socket head	114
2 - 7	

<u>DESCRIPTION ITEM</u>	<u>Item No.</u>
Motor bolts, Base bearing to base M4 x 10 Elbow spindle hex hd	115
Hand to finger, hand to bevel gear M3 x 6 cheese hd	116
Shoulder spindle M5 x 10 hex hd	117
General sheet metal fixing M3 x 6 hex hd	118
M4 Nuts	119
M4 Washers	120
M4 Shakeproofs elbow spindle	121
M5 shakeproofs shoulder spindle	122
M3 Nuts	123
M3 washers - switches	124
6mm steel balls - base bearing	125
Magnetic reed switches	010(101?)
Driver board	126
Interface board	127
Edge connector	128
6mm Washers	129
Roll pins	130
4.5mm circlips	131
3mm circlips	132
Elbow spacer	133

2.5 ASSEMBLY

Preparation

Study the parts list, drawings and the parts themselves until you are sure you have identified them all. Assemble the tools suggested in the list of tools (2.3). Read carefully technical hints section. Solder 12 inches of ribbon cable to each motor. Glue magnets (101) into the slots in the reduction gears, noting that the hand gear (25) needs no magnet. Check that the adjusting ring (14) of the main bearing screws easily onto its base. Clean both if necessary. Insert bushes into the arms, if necessary using a vice, but taking care not to distort the sheet metal.

Construction

Fit base bearing support (2) column inside base (1). (M4 bolts, nuts.) NB NUTS INSIDE BASE

Bolt 1 motor (shorter cable) inside base. (M4 hex bolts, washers on motor side - nuts on inside). Fit pulley to spindle base of motor with the grub screw at the top (04b). Fit base reduction gear spindle (07) to base. (Thick turned washer, M4 hex bolt) Fit reduction gear and belt. Place a small drop of oil on the reduction gear spindle before fitting reduction gear.

When fitting belts they should be placed fully on the motor spindle and worked gently onto the reduction gear, a small section of their width at a time. (see general hints on lubrication)

Fit base switch support. (M3 hex bolt) NB DRAWING FOR POSITION. Fit base switch and run wires through adjacent hole. (M3 x 10 cheesehead, washer)

Fit bearing ring (12) (long spigot down) through shoulder base pan (11) from inside. The base gear (13) fits on the lower face of the pan, with the magnet at 2 o'clock as seen from inside the pan with the flange at the top. (M4 countersunk x 16mm bolts, nuts)

(This step and the next are simpler with some help from an assistant). Put shoulder base pan (gear side up) on to 3in supports (books etc,) so that the bearing support column can be inserted. Practise this movement to make sure all is well. Smear vaseline from a fridge, or grease on the bearing track of the flange, and using tweezers to avoid melting the vaseline carefully place 24 ball bearings round the flange, embedding them into grease. There will be a slight gap when all the balls are in place. Invert the base and insert the threaded bearing support column inside the bearing ring taking care not to dislodge any of the balls so that the base pan meshes with the base gear. Keep the two parts level in the same relationship by taping the parts together with a piece of wood or a spanner 5mm thick between the motor pulley and the shoulder base pan.

Large rubber bands can be used instead of tape. An assistant to hold the parts for you will be useful here.

Turn the assembly the other way up (the base is now on the bench with the shoulder base pan above it. Put more grease round the bearing track and embed 24 more ball bearings in it. Gently lower the adjusting ring (14) on to the threaded base and then screw the finger tight, remove with tape, adjust the ring until the base pan moves freely without play then tighten the grub screw, inserting a small wood plug to protect the bearing thread. (M4 grub screws)(102). The bearing may need adjusting after some use as it beds in.

Fit hand motor bracket (15) to shoulder base pan (M3 bolts) then the hand motor O3h(M4) and the hand motor pulley. Then fit the hand reed switch-bracket (M3) and the switch (M3 x 10 cheesehead bolts).

Fit motors to the shoulder side plates (17) and feed the cables through the holes towards the inside. The bolts which are next to the reduction gears should be placed nut out to prevent the reduction gears catching on the end of the bolts. Fit correct pulleys (04u/f/w) to the motor spindles noting which pulleys from the drawing, tighten the grub screws.

Fit the shoulder plates. This is simplified by loosely tightening the end bolts to support the weight. Feed the motor cables down through the main bearing (M3).

Slide switch support (19) bar through spacers (18), switches (101) and motor support bracket (see drawing for correct order of spacers). You will need to be able to adjust the position of the reed switches after the arm is fitted so that they clear the gear wheels ie tangential to shoulder pivot. Fit the motor support stiffener bar and spacers. Leave nuts finger tight. (M3 nuts).

Assemble reduction gear support bar (21), assemble with the correct length drive belts (08s/m/l) over each gear, reduction gears facing in correct direction and the thin metal M6 washers at either end. (see drawing) Slide gently into position and bolt in the support bolts (M4 a 10mm) Fit the belts round the motor pulleys.

Put upper arm drive gear on the outside of the upper arm side plate. The magnet should be at 1 o'clock, viewed from the gear side of the arm. (M3 CSK screws x 6mm) Fit a brace to one upper arm side piece (22), then fit the other side piece to the brace. Fit all bolts and nuts before tightening any of them. Check 8mm shoulder spindle (29) slides freely through accute bushes in upper arm side pieces and through bores of drive gears, pulleys and spacers. Assemble by sliding shaft from one side and threading gears, pulleys and spacers on in the correct order of orientation - use drawing.

Fit pulley (32) to the outside of the forearm side plate (30) (M3x6mm)(countersunk screws). Fit a brace to one forearm side plate, then fit the other side plate to the brace. Check for squareness before finally tightening bolts.

Put elbow pivot through bushes and an 8mm bar through wrist bushes. (M3 bolts, nuts) Check fit before assembly. Assemble the pulleys (33) on the elbow spindle (34), lubricate and fit it to the large arm, and bolt through into spindle. (M4 bolts, washers)

Assemble the wrist bevel gear carrier (35) and wrist pulleys (36) and then tap the roll pins gently home with a small hammer, supporting aluminium gear carrier to prevent distortion.

Fit the wrist gears on the bushes (37) from the outside. Fit bevel gear carrier (35) between the wrist bevel gears (37), line up holes in end of wrist pivot (38) bores with tapped hole in carrier by peering down pivots. If you do not have a screw gripping or magnetic driver use a little piece of masking tape or sellotape to fix M3 cheesehead screw to the end of your screwdriver in such a way that it will pull off after tightening - check gears pivot freely on pivots and that the whole assemble can pivot in oilite bushes (drops of oil on faces of gears and pivots)

Screw the finger support flange (40) to the hand bevel (39). (M3 x 6mm cheesehead screws) Screw the hand pivot (41) to the bevel gear carrier (35). Tighten on a drop of loctite if available, gently by turning a pair of pliers inside it. The bevel gears should be positioned with their grub screws pointing towards the hand when the hand and the forearm are in line (see drawing).

Assemble the fingertip (42) and cable clamp (43) with the small spring (44) on the pivot (45), and clip together with large circlips on the cable clamp. The spring should be positioned so that the "back" of the spring is on the knuckleside of the fingertip, thus tending to open the hand.

Assemble the middle finger (46) and its pivot (47) with the large spring (48). Fix to the finger base (49) with the long pin (50/L) (16mm x 3mm) and two small circlips (see drawing). Fix one circlip to the pin before one begins to assemble.

Join the fingertip to the middle section with the short pin (50/S) (13mm x 3mm) and two small circlips.

Cut off one end of the tip spring about 8mm-10mm beyond its hole. Level with its hole bend the spring through a right-angle to secure it. Repeat at the other end. Trim the inner end of the middle finger spring flush with the end of the finger end and treat the outer end as above.

Fit the small pulley (51) to the finger middle section using a short pin (13mm x 3mm) and two small circlips. Fit the larger pulley (52) to the finger base with a long pin (16mm x 3mm) and two small circlips.

Screw the finger base to the finger support flange. Make sure that the fingers are evenly spaced and do not interfere with each other, and then tighten. (M3 x 6mm cheesehead)

Assemble the large and small hand sheave pulleys using the large circlip on hand sheave pin (55).

CABLE THREADING

Slide arm into shoulder, you will need to align the reduction pulleys between the main drive gears as you lower the arm into place, and assemble using M5 hex head bolts and shakeproof washers. Tighten and check the reduction gears "mesh" correctly and the arm moves freely.

Connect grip action cable tail to shoulder base pan via the spring correctly placed over the pulley and tension using the normal method with the cable clamp.

Glue strips of rubber to finger tips using superglue.

The driver and interface board should be bolted to the base pan using the spacer bars (58) and spacers. Bolt base pan (57) to base (M3 x 6mm hex head).

Hints: Useful tools are:

a) 2 or 3 'bulldog clips' to maintain the tension in the cable over completed sections of each cable while the remainder is threaded. Masking tape can also be used for this purpose,

b) Ends of the cable can be prevented from fraying by placing a drop of 'superglue' on the end of area where it is to be cut. The excess should be wiped off on a piece of paper.

NB. This process also stiffens the end which is useful when threading the cable through the pulleys.

c) Ensure all grub screws are in position but are not obstructing the cable holes. Also check there are no burs remaining from machining blocking the holes.

d) The cables can be threaded before the arm is bolted for the shoulder which eases the problems of access considerably. The 'grip action' cable tail can be taped or clipped to the arm and connected and tensioned with its spring after the arm is fitted to the shoulder,

e) When tensioning the cable, if it is passed through the clamp and back, then connected to the spring adequate tension can be applied by pulling the 'free tail' and then nipping it with the grub screw. A friend will be useful if around, but it is quite possible without. The correct tension can be easily judged, as when completed the coils of the spring should be just separated, though this is not critical.

- f) During threading the correct 'route' can be ascertained from the expanding drawings. It is very important these should be followed exactly, especially the position of the grub screws when they are tightened on the cable. If this is wrong it will affect the performance of the arm.
- g) Care should be taken to avoid the cable kinking or crossing itself on the drums.
- h) Experience has shown that the best order to thread the cables and lengths to use. (Excess can be trimmed easily later but makes tensioning simpler)

First - Wrist cables one at a time. 1.47m (each)

Second - Elbow cable (set up the spring pillar first - M3 x 10mm cheesehead and 2 M3 hex full nuts) attach crimped cable clamp to forearm first using M3 x 10 cheese head and two nuts as a cable pillar. 0.95m

Third Single finger cable (fix to the hand sheave pulley using M3 x 6mm cheesehead and crimped cable clamp. 0.18m

Fourth - Double finger cable (loop over small hand sheave pulley on grip action pulley and adjust so that G A P is even when pulleys are evenly positioned). 0.36m

Fifth - Grip action cable (start at end fixed in cable drum and stick other end to arm while fitting it to the shoulder then tension with the spring to the shoulder base pan). 1.3 m

- i) Ends using the crimped cable eyelets should be threaded through the eyelet and a small thumb knot tied to prevent the cable slipping before crimping the bracket using crimping or ordinary pliers. So not crimp too tight or you may cut through cable, though KEVLAR is very tough,

To enable the Arduino to function with
E microprocessor equipment as possible, the
board is standard 8-bit bidirectional port
or non-latched. If non-latched, the data
is used to input data to the micro.

L

To the output side the port is configured
lines are defined as four data bits (D4-D7)
E and one bit (D0) to identify the
level of the port. Four data lines are
used to control the stepper motor coils.

E

The address C bits are used to channel the
selected motor. The three address bits
of which 1-3 are used to select one of 8
0 and 7 are unallocated.

C

T

D1 indicates the direction of data travel
D1 is low from the microswitch, if high
R high. The transition of D1 from high to
low causes the step pattern to be latched
output latch.

R

If the input side O = D1 are used to read
O the data. These read switches and delays
input for each of the movements of the
step pattern points for latching the step
N pattern.

O

N

D1 is phase. D1 is an 8-bit which
I data is read from the system, allowing the
data to be read back to the system.

I

The interface circuitry consists of twelve
C chips. The data bus route is out to the
12-bit. 12-bit and 12-bit control the data bus
latches. 12-bit decodes the three input
S lines. six of which are for

C

S

ELECTRONICS

3.1 Description

The Interface

To enable the Armdroid to function with as wide a range of microprocessor equipment as possible, the interface is designed round a standard 8-bit bidirectional port. This may be latched or non-latched. If non-latched, the interface will normally be used to input data to the micro.

In the output mode the port is configured as follows. The eight lines are defined as four data bits (D8-D5), three address bits (D4-D2) and one bit (D1) to identify the direction of data travel on the port. Four data lines are provided so that the user can control the stepper motor coils direct from computer.

The address bits are used to channel the step pattern to the selected motor. The three address bits can define eight states, of which 1-6 are used to select one of the motors, while states 0 and 7 are unallocated.

D1 indicates the direction of data travel, to the motors when D1 is low, from the microswitches, if installed, when D1 is high. The transition of D1 from high to low generates a pulse which causes the step pattern to be latched into the addressed output latch.

In the input mode D8 - D3 are used to read the six microswitches on the arm. These reed switches and magnets provide a "zero" point for each of the movements of the arm, which can be used as reference points for resetting the arm in any position before a learning sequence begins.

D2 is spare. It is an input bit which can be buffered and used for an extra input sensor, allowing the user to connect a 'home brew' transducer to the system.

The interface circuitry consists of twelve TTL components which decode the data and route it out to the selected motor driven logic. IC1 and IC2 buffer the data out to the decoder and latches. IC6 decodes the three input address bits to provide eight select lines, six of which are for the latches IC7 - IC12.

INTERFACE ONLY

D1 is buffered and fed into a monostable (IC4) to generate a clock pulse. This causes the decoder to provide a latch pulse for approximately 500ns to the addresses motor control latch. D1 is tied to pull-up resistor (R1) so that the line is high except when are output from the microprocessor. The buffers IC1 and IC2 are enabled by the buffered output of bit 1 so that data are fed to the latch inputs only when bit 1 is low. The bit 1 buffer is always enabled because its enable is tied low.

The microswitch inputs are buffered by IC5 which is enabled by the complemented output of bit1, so that when bit1 is high IC5 is enabled, and the contents of the microswitches will be input to the microprocessor. This allows the user to operate the arm under bit interrupt control, giving instant response to a microswitch change and avoiding having to poll the microswitches. The six microswitch inputs are pulled up; thus the switches can be connected via only one lead per switch, with the arm chassis acting as ground.

THE MOTOR DRIVERS

the motor drivers are designed so that the arm can be driven from the output of the computer interface circuitry.

The six motor driver stages need two power supplies: 15v at about 3A and 5v at 150 MA.

The four waveforms QA-QD are then fed into IC's 13-16 which are 7 x Darlington Transistor IC's. These provide the high current needed to drive the stepper motor coils, the driving current being about 300 MA at 15v.

INTERFACE DRIVER BOARD

ITEM	VALUE	QUANTITY
Resistors		
R1	1K0	
R2	10K	
R3-8	2K2 resitor network	1
R9	1K8	
R10	1K8	
R11	1K8	3
R12	15K	1
R13	10K	2
R14	18ohm 5w	1
R15-R20	1K0	6
Capacitors		
C1	100p polystyrene	1
C2	1.0vf Tant	1
C3-C15	10nf ceramic	13
Semiconductors		
IC1	74LS 125	
IC2	74LS 125	
IC3	74LS 04	
IC4	74LS 123	
IC5	74LS 366	
IC6	74LS 138	
IC7-IC12	74LS 175	
IC13-IC16	ULN2003A	
IC17	UA 7805	
ZD1	BZX 13v ZENER	
Miscellaneous		
MXJ 10 way edge connector		
5 way PCB plug and socket connector		
Through Pins		
16 pin IC sockets		
14 pin IC sockets		
4 way modified PCB plug and socket		

GENERAL ASSEMBLY SEQUENCE FOR THE PC BOARD

- A Fit all of the through pins to the board.
- B Fit and screw the 5v regulator to the board.
- C Identify and fit the resistors and the 13v zener to the board. The black band v points to the motor connectors (on the zener DIODE).
- D Identify and fit all capacitors to the board.
- E Solder the 2k2 resistor network, IC sockets, and the 4 and 5 way PCB plugs to the board.
- G Solder the 10 way socket to the board.

NOTE:

Refer to the overlay diagram and parts list to ensure that the resistors, capacitors, IC,s and other parts are inserted into the correct locations on the PC Board.

BASIC BOARD CHECKS

- A Check the board for dry joints and re-solder any found.
- B Hold the board under a strong light source and check the underside to ensure there are no solder bridges between the tracks.

FITTING THE PC BOARD TO THE BASE OF THE ROBOT


The PCB should be fitted to the base plate using the nylon pillars provided.

MOTOR CONNECTION

Connect the motors to the 5way sockets, ensuring correct 15v polarity, via the ribbon cable, referring to the diagram provided to ensure correct connection.

POWER CONNECTION

Connect the power to the modified 4way socket ensuring correct polarity as shown below.



Polarising pin

Blue - Pin 1 on I/P connector=0v 15v = Brown = Pin 2 on I/P connector


NOTE

A number of diagrams are given, explaining in detail the interconnections between the motors and the PCB, if the motors are connected in the manner shown then the software provided will map the keys 1-6 and q,w,e,r,t,y to the motors in the following way

1, q, = GRIPPER. 2, w, = left wrist. 3, e, = right wrist.
4, r, = forearm. 5, t, = shoulder. 6, y, = base.


as shown in the diagram, the two middle pins of the stepper motors should be connected together and to 15v.

Motor Connection And Designation Layouts




Ribbon Cable To Stepper Motor Connections

- Qa Black or Green
- Qb Red or Purple
- Qc Brown or Blue
- Qd Orange or Grey
- +15v Yellow or white



Motor Assignments To Functions

- Motor 1 = Grip
- Motor 2 = Left Wrist
- Motor 3 = Right Wrist
- Motor 4 = Elbow
- Motor 5 = Shoulder
- Motor 6 = Base



...with the necessary part, and ...
...the leading tasks with variations of
...of course, but of course you write
...language they showed.

S

...type SYSTEM, press ENTER, answer the
...main. The program will be
...loaded. Answer the next question

O

...described.

F

...man-oriented program for teaching the
...downwards which it will then repeat as
...as you like. The program is divided into
...the section and for fine-tuning
...the tape and load it again, one for
...inserting modules, and finally the

T

...that, if this is your first encounter
...read quickly through the comments with
...understanding all the details. Then go
...the 'Sequence for new users'. This will
...at the program does. A

W

A

...tion

R

...without comments in
...commands explained under MESSAGES. You
...g D (here), press G(0), and the program
...you have taught it.

E.

...g L(LAN) you will be asked whether you

4. SOFTWARE

4.1 Introduction

A machine code program, LEARN , to drive the ARMDROID has been specially written. It was designed for the Tandy TRS-80 Model 1 Level 11, and the loading instructions given here apply to that computer. But the program can be easily adapted to any Z80 microprocessor with the necessary port, and versions made available for the leading makes with variations of these instructions where appropriate. But of course users can write their own software in whatever language they choose.

4.2 Loading

When in Basic type SYSTEM, press ENTER, answer the '*' with LEARN and then press ENTER again. The cassette tape will take about 1.5 minutes to load. Answer the next '*' with / 17408 and press ENTER.

4.3 General Description

LEARN is a menu-oriented program for teaching the ARMDROID a sequence of movements which it will then repeat either once or as many times as you like. The program is divided into four sections, one for learning the sequence and for fine-tuning it, one to save the sequence on tape and load it again , one for moving the arm without the learning function, and finally two exit commands.

We suggest that, if this is your first encounter with the program, you should read quickly through the commands without worrying too much about understanding all the details. Then go to Section 4.5 and follow the 'Sequence for Newcomers'. This will give you a good idea of what the program does. After that you can begin to discover some of the subtleties of planning and fine-tuning sequences of movements.

4.4 Explanation

L(EARN)

Stores a sequence of manual movements in memory. The arm is moved using the commands explained under M(ANUAL) . You can exit the command by pressing 0 (zero) , press G(0), and the arm will repeat the movement you have taught it.

On pressing L(EARN) you will be asked whether you want to S(TART) again or C(ONTINUE) from the current position. The first time press S(TART) . The arm is then free to be moved by hand without the motors' torque preventing you. Move it to a suitable starting position, then press the space bar. You will find that you cannot now move the arm by hand.

To add a sequence already in memory press C(ONTINUE) instead of S(TART).

Using the manual commands, move the arm to another position. As it goes the computer is adding up the steps each motor is making, either forward or back, and storing the data in memory. (holding the space bar down during manual control slows the movement)

Exit by pressing 0 (zero).

D (ISPLAY)

Displays the sequence stored in memory. The sequence can be edited with the E(DIT) command.

The six columns of figures correspond to the six motors, and the order is the same as that of the 1-6/Q-Y keys (see M(OVE)). The first row (RELPOS) shows the current position. Each row represents a stage of the movement, and the actual figures are the number of steps each motor is to make, positive for forward, negative for reverse. The maximum number of steps stored in a row for one motor is +127 or -128, so if a movement consists of more than this number it is accomodated on several rows.

Movements of the arm can be fine-tuned by editing (see E(DIT)) the figures on display until the arm is positioned exactly.

Scrolling of the display can be halted by pressing 0 (zero). To continue scrolling, press any other key. To display the figures one after the other, keep pressing 0.

E(DIT)

Allows the user to change the figures in the memorised sequence.

Truncate a sequence by pressing R(OW COUNT), then ENTER, then the number of the last row you want performed, and finally ENTER. This clears the memory from the next step onwards, so you should only do this if you do not want the rest of the sequence kept in memory.

By pressing M(OTOR STEP), you can change any of the numbers in any row and column.

S(ET ARM)

Sets the current position of the arm as the 'zero' or starting position.

When pressed from the Menu, it simply zeroes the first row of the display.

S(ET ARM) has another function. During a L(EARN), pressing S(ET ARM) at any moment when the arm is at rest will ensure that the movements before and after are separated from each other instead of being merged. This is the way to make quite sure that the arm passes through a particular point during a sequence. Try the same two movements without pressing S(ET ARM), and note the difference in the display.

It is important to realise that, if a sequence has been memorised and S(ET ARM) is pressed from the Menu when the arm is not in its original starting position, pressing G(0) will take the arm through the sequence but from the new starting point. This can be useful for adjusting the whole of a sequence (perhaps slightly to right or left), but it can lead to the arm running into objects if the new starting point is not selected with care.

W(RITE)

Writes a memorised sequence to cassette tape.

R(EAD)

Reads a previously written sequence from cassette tape into memory.

C(CHECK)

Compares a sequence written to cassette tape with the same sequence still in memory, to verify the tape.

G(0)

Moves the arm through a memorised sequence, either once or repeatedly.

It is important to make sure that the starting point in memory is the right one, or the sequence may try to take the arm into impossible positions, (see S(ET ARM))

T(0 START)

Takes the arm back to the zero or starting position.

F(REE)

Removes the motors' torque from the arm, thus allowing it to be moved by hand.

M(ANUAL)

Gives the user control of the movements of the arm direct from the keyboard. It is used (a) for practising manual control before L(EARN)ing, (b) for trying new combinations of separate movements, and (c) for moving the arm to a new starting position before pressing S(ET ARM). Holding the space bar down slows the movement by a factor of about 3.

The motors are controlled with the keys 1-6/Q-Y. The keys operate in pairs, each pair moving a motor forwards and backwards. Any combination of the six motors may be moved together (or of course separately), but pressing both keys of a pair simply cancels any movement on that motor.

The geometry of the arm is designed to give the maximum flexibility combined with maximum practicality. A movement of one joint affects only that joint: with some designs one movement involuntarily produces movement in other joints.

It is a feature of the ARMDROID that it has a so-called 'parallelogram' operation. Starting with the upper arm vertical, the forearm horizontal and the hand pointing directly downwards, the shoulder joint can be rotated in either direction and the forearm and hand retain their orientation. Equally the forearm can be raised and lowered while leaving the hand pointing downwards. Moving the arm outwards and down by rotating both the shoulder joints together still leaves the hand vertical. This is of vital importance for simplifying the picking and placing of objects.

The motors controlled by the keys are:

1/Q: Gripper
2/W: Wrist left
3/E: Wrist right
4/R: Forearm
5/T: Shoulder
6/Y: Base

B(OOT)

Returns the computer to the program start and clears the memories.

Q(UIT)

Returns the computer to TRS80 System level.

ARM TRAINER MK2AL
DIRECT FULL STEP MOTOR CONTROL
FOR TRS80 MODEL 1, LEVEL 11

BY ANDREW LENNARD

*** July 1981 ***

S E C T I O N 1

A S Y S T E M E Q U A T E S

B S Y S T E M V A R I A B L E S

C S Y S T E M C O N S T A N T S

4.5 INTRODUCTORY DEMONSTRATION SEQUENCE

1. After loading the program, the screen shows the menu. Press L to enter L(EARN).
2. Screen: START AGAIN OR C(ONTINUE) FROM PRESENT POSITION, (.) TO EXIT. Press S
3. Screen: " ARM RESET
ARM NOW FREE TO MOVE
TYPE SPACE BAR WHEN READY, OR FULL STOP TO EXIT"
Now move the arm so that both arm and forearm are vertical with the hand horizontal. For coarse movements grasp the forearm or upper arm and move it. For fine adjustments and for movements of the hand, it is better to use the large white gear wheels in the shoulder joint. Press the space bar and the arm will become rigidly fixed.
4. Screen: "*** TORQUE APPLIED ***"
You can now move the arm using the 1-6/Q-Y keys as explained in the manual section. Try just one movement alone at first. Now press 0 (zero) to exit from L(EARN). The arm will return to the starting position, and the Menu appears on the screen.
5. Screen: Menu. Press D for D(ISPLAY).
6. Screen: Display and Menu. The numbers of steps you applied to each motor have been memorised by the computer, and these steps are now displayed see D(ISPLAY) section for explanation. Press G for G(0).
7. Screen: "DO (F) OREVER OR (O) NCE?. Press O (letter O), and the arm will repeat the movement it has learnt.
8. Screen: "SEQUENCE COMPLETE" and Menu. Press L.
9. Screen: as 2 above. This time press C. Now you can continue the movement from this position, using the 1-6/Q-Y keys as before. Now press 0 (zero). Again the arm returns to its original position.
10. Screen: Menu. Press D
11. Screen: Display and menu. Your new movement has been added to your first. Press G.
12. Screen: as 7 above. This time press F. Each time a sequence is started a full point is added to the row on the screen. To stop press full point.

This is a very simple demonstration of how complex movements can be built up, learnt as a sequence and then repeated endlessly and with great accuracy.

SYSTEM EQUATES

```
PORT    EQU    0 4    ; ARM PORT NUMBER
FINAD   EQU    02B2   ; SYSTEM RESTART
PCHR    EQU    0033H  ; SYSTEM PRINT CHARACTER
GCHR    EQU    0049H  ; SYSTEM GET CHARACTER
KBD     EQU    002BH  ; SCAN KEYBOARD
PUTSTR  EQU    28A7H  ; SYSTEM PRINT STRING
CASON   EQU    0212H  ; CASSETTE ON
CASOF   EQU    01F8H  ; CASSETTE OFF
RDHDR   EQU    0296H  ; READ HEADER ON CASSETTE
READC   EQU    0235H  ; READ CHARACTER FROM CASSETTE
WRLDR   EQU    0237H  ; WRITE HEADER TO CASSETTE
WRBYA   EQU    0264H  ; WRITE CHARACTER TO CASSETTE
MINUS   EQU    '-'    ; ASCII MINUS
SPAC    EQU    ' '    ; ASCII SPACE
NL      EQU    0DH    ; ASCII NEW LINE
NUMBA   EQU    30H    ; ASCII NUMBER BASE
MAXLE   EQU    10     ; UPPER BOARD FOR ARST ROW COUNTER

;   ORG      1740 8   ; = 4400 TRS80 HEX ADDRESS
;             ; FOR START OF PROGRAM
```

VARIABLES USED

MIN	DEFB 00	; Has value of one if number input negative
MAN	DEFB 00	; If MAN = zero then steps are stored
STRFG	DEFS 00	; If STRFG non zero then store TBUF array
KEYP	DEFB 00	; Set if key pressed in KEYIN Routine
FORFG	DEFB 00	; Set if sequence to be done forever
COUNT	DEFB 0000	; Number of motor slices stored
CUROW	DEFB 0000	; Pointer to next free motor slice

ARRAYS

NUMAR	DEFS 10	; Store used for Binary to ASCII Conversion ; Routine CTBAS
POSAR	DEFS 12	; Each two bytes of this six element array ; contain one value which is used to ; keep track of each motor's motion, ; hence the array can be used to reset ; the arm, moving it into a defined ; start position. ; Each 16 bit value stores a motor's ; steps in two's complement arithmetic.
CTPCS	DEFS 6	; 6 Bytes, each relating to a motor. ; A number from 1-4 is stored in ; each byte and this is used to ; index the FTABL (see constant definition)
TBUF	DEFS 6	; When learning a move sequence the ; six motors' motions are stored in this ; six byte array. Each byte relates ; to a motor and holds a motor step ; count in the range -128 to +127 ; If the motor changes direction or a ; count exceeds the specified range then ; the whole TBUF array is stored in ; the ARST array and the TBUF array ; is cleared. ; TBUF means temporary buffer.
DRBUF	DEFS 6	; Each byte relates to the previous ; direction of a motor.
MOTBF	DEFS 6	; A six byte array used by DRAMT to ; tell which motors are being driven, and ; in which direction. ; Bit zero set if motor to be driven. ; Bit one set if motor in reverse ; Byte zero if motor should not be driven.
ARST	DEFS N*6	; This array holds the sequence that ; the user teaches the system. The array ; consists of N*6 bytes where N is ; the number of rows needed to store the ; sequence.

CONSTANTS USED

```
FTABL      DEFB 192    ;  
           DEFB 144    ;  
           DEFB  48    ;  
           DEFB  96    ;
```

```
 ; FTABL is a small table which defines the  
 ; order of the steps as they are sent out  
 ; to the arm. To drive each motor the  
 ; DRAMT routine adds the motor's offset  
 ; which is obtained from CTPOS and adds  
 ; this to the FTABL start address -1. This  
 ; will now enable the DRAMT routine to  
 ; fetch the desired element from the FTABL  
 ; array, and this value is then sent to  
 ; the motor via the output port.
```

CONSTANTS AND ARRAYS
STRINGS

```

MK (AL2) SIGON      DEFM          *** COLNE ROBOTICS ARM CONTROLLER
          ***'
          DEFW          000DH
RELYQ    DEFB          0DH
          DEFM          'REALLY QUIT? (Y/N)'
          DEFW          00
SIGOF    DEFW          0D0DH
          DEFM          'YOU ARE NOW AT TRS80 SYSTEM LEVEL'
          DEFW          00
ECOMS    DEFM          'EDIT (M)OTOR STEP, OR (R) OW COUNT?'
          DEFW          000DH
COUTS    DEFM          'NEW UPPER ROW BOUND IS?'
          DEFB          00
EDSTR    DEFM          'ROW NUMBER?'
          DEFB          00
BADMS    DEFM          '*** BAD INPUT VALUE ***'
          DEFW          000DH
MOTNS    DEFM          'CHANGE STEPS ON WHICH MOTOR?'
          DEFB          00
NVALS    DEFM          'REPLACEMENT STEP VALUE?'
          DEFB          00
QUEST    DEFM          'LRN, READ, CHECK,WRITE, GO, DISP, BOOT, MAN,
          DEFW          QUIT, SETA, TOST, EDT, FREE
          DEFW          000DH
RORNM    DEFM          'DO (F)OREVER OR (O)NCE?'
          DEFB          00
CASRD    DEFM          'TYPE SPACE BAR WHEN READY, OF FULL STOP TO EXIT
          DEFB          00
QMESS    DEFM          'PARDON'
          DEFW          000DH
BOOTS    DEFB          0DH
          DEFM          'WANT TO RE-START (Y/N)?'
RELNS    DEFM          'START AGAIN OR (C)ONTINUE FROM CURRENT POSITION
          DEFW          (.) TO EXIT
          DEFW          000DH
DISPS    DEFB          0DH
          DEFM          ' *** MOVEMENT ARRAY DISPLAY *** '
          DEFB          0DH
          DEFW          000DH
NODIS    DEFM          '*** NO SEQUENCE IN STORE ***'
          DEFB          0DH
          DEFW          000DH
OVFMS    DEFM          'NO MORE ARM STORE LEFT, DELETE OR SAVE?'
          DEFW          000DH
DONMS    DEFB          0DH
          DEFM          'SEQUENCE COMPLETE'
          DEFW          000DH
RDMSG    DEFM          '*** READ ERROR ***'
          DEFW          000DH
TAPOK    DEFM          '*** TAPE OK ***'
          DEFW          000DH
STRST    DEFM          'ARM RESET'
          DEFW          000DH
NOTOR    DEFM          'ARM NOW FREE TO MOVE'

```

```
TORMS  DEFB 000DH
        DEFB 0DH
        DEFM '*** TORQUE APPLIED ***'
        DEFW 000DH
POSST  DEFM 'RELPOS='
        DEFB 00
```

S E C T I O N 2

Learn a sequence command
 Edit a sequence command
 Load in sequence from tape command
 Write sequence to tape command
 Check stored sequence command
 Restart system command
 Exit from system command
 Set start position command
 Move arm to start position command
 Print all arm data
 Load into manual mode
 Execute stored sequence command
 Display stored sequence command

C

O

M

M

A

N

D

R

O

U

T

I

N

E

S

COMMAND INDEX

STARM Program entry point
LEARN. Learn a sequence command
EDIT. Edit a sequence command
READ. Read in sequence from tape command
WRITE. Write sequence to tape command
CHECK. Check stored sequence command
BOOT. Re-start system command
FINSH. Exit from system command
SETARM. Set start position command
TOSTM. Move arm to start position command
FREARM. Free all arm joints
MANU. Go into manual mode
GO. Execute stored sequence command
DISPLAY. Display stored Sequence command

MAIN LOOP

```

; Program start

STARM      CALL CLRSC      ; Clear the TRS80 Screen
           LD   HL,SIGON   ; Point to sign on message
           CALL PSTR       ; Print it
           CALL PNEWL      ; Print a new line
           CALL INIT       ; Set up system
QUES1      CALL DELT       ; Small delay
           LD   HL,QUESS   ; Point to menu string
           CALL PSTR       ; Print it
           CALL GCHRA      ; Get response and print it
           CALL PNEWL      ; Print new line
           CP   NL         ; Is response a newline
           JR   Z,QUES1    ; Yes then ignore
           CP   'L'        ; Is response an 'L'
           JP   Z,LEARN    ; Yes do learn section
           CP   'E'        ; Is it an 'E'
           JP   Z,EDIT     ; Yes do edit
           CP   'R'        ; Is it an 'R'
           JP   Z,READ;    ; Yes then do read command
           CP   'W'        ; Is it a 'W'
           JP   Z,WRITE    ; Yes do write command
           CP   'C'        ; Is it a 'C'
           JP   Z,CHECK    ; Yes do check routine
           CP   'S';       ; Is it an 'S'
           JP   Z,SETAM    ; Yes then do arm set
           CP   'T' ;      ; a 'T'
           JP   Z,TOSTM    ; Yes then move arm to start
           CP   'G';       ; a 'G'
           JP   Z,GO;      ; Do execute movements stored
           CP   'D';       ; a 'D'
           JP   Z,DISP;    ; Yes then display ARST array
           CP   'B';       ; a 'B'
           JP   Z,BOOT     ; Yes then restart system
           CP   'M';       ; an 'M'
           JP   Z,MANU;    ; Yes the Manual control of arm
           CP   'F';       ; a 'F'
           JP   Z,FREARM;  ; Yes then clear all motors
           CP   'Q';       ; a 'Q'
           JP   Z,FINSH    ; Yes then quit program
           LD   HL,QMESS   ; Point to 'PARDON' message
           CALL PSTR       ; Print it
           JP   QUES1;     ; Try for next command

```

THE LEARN ROUTINE

; This section deals with the recording
; of an arm sequence

```

LEARN      LD      HL,RELNS ; Point to learn message
           CALL    PSTR     ; Print the message
           CALL    GCHRA    ; Get response and print it
           CALL    PNEWL    ; Print a new line
           CP      '.'      ; Response a '.'
           JP      Z,QUES1   ; Back to main loop is uder types a '.'
           CP      'S'     ; Response an 'S'
           JR      Z,WAIT1  ; Learn sequence from start
           CP      'C'     ; a 'C'
           JR      Z,NOINT  ; Continue learning from end of
                           ; sequence
           CALL    PNEWL    ; output a new line
           JR      LEARN    ; Bad answer so try again
WAIT1      CALL    MOVTO    ; Move arm to start position
           CALL    INIT     ; Clear variables
WAIT2      LD      HL,CASRD ; Point to waiting message
           CALL    PSTR     ; Print it
           CALL    GCHRA    ; Get response and print it
           CALL    PNEWL    ; Print new line character
           CP      '.'      ; Response a '.'
           JP      QUES1    ; Exit to main loop if so
           CP      SPAC     ; Is it a space?
           JR      NZ,WAIT2 ; If not then bad input, try again
           CALL    TORQUE   ; Switch motors on
           JR      STLRN    ; Do rest of learn
NOINT      LD      HL,(COUNT) ; Get current count
           LD      A,L      ; Is it zero?
           OR      H
           JR      Z,NOSTR  ; Yes then can't add to nothing
STLRN      XOR     A        ; Clear manual flag
           LD      (MAN)A   ; Because we are in learn mode
CONLN      CALL    KEYIN    ; Drive motors and store sequence
           OR      A        ; Zero key pressed
           JR      NZ,CONLN ; No then continue
           CALL    MOVTO    ; Move arm to start position
           JP      QUES1    ; Back to main loop

```

EDIT FUNCTION

```

EDIT      LD      HL,(COUNT)    ; Get row count
          LD      A,L            ;
          OR      H              ; Test for zero
          JP      Z,NOSTR        ; Yes then nothing in store
EDSRT     LD      HL,ECOMS        ; Print edit message
          CALL    PSTR           ;
          CALL    GCHRA          ; Get response
          CALL    PNEWL         ; Print a new line
          CP      'M'           ; Is response an 'M'
          JR      Z,EDMOT        ; Yes then edit motor
          CP      'R'           ; Is response an 'R'
          JR      NZ,EDSRT       ; No then try again
          LD      HL,COUTS       ; HL = New row count message
          CALL    PSTR           ; Print it
          CALL    GINT           ; Get 16 bit signed integer
          JP      NZ,BADC        ; Non zero return means bad input
          LD      A,H            ; Test top bit of HC
          BIT     7,A            ;
          JP      NZ,BADC        ; If negative then bad input
          LD      BC,(COUNT)    ; Get count value
          PUSH   HL              ; Save response
          OR     A                ; Clear carry flag
          SBC   HL,BC            ; See if response < current count
          POP    HL              ; Restore response
          JR     NC,BADC         ;
          LD     (COUNT),HL     ; Replace count with response
          JP     QUES1           ; Back to main loop
EDMOT     LD      HL,EDSTR       ;
          CALL   PSTR            ; Print 'row number'
          CALL   GINT            ; Get integer response
          JR     NZ,BADC         ; Bad answer
          LD     A,H             ;
          BIT    7,A             ; No negative row count
          JR     NZ,BADC         ; allowed
          LD     A,H             ;
          OR     L                ; or zero row count
          JR     Z,BADC          ;
          LD     BC,(COUNT)     ; Get row count into BC
          INC    BC              ; Move count up one
          PUSH  HL               ; Clear carry flag
          SBC   HL,BC            ; Subtract count from response
          POP   HL               ; Restore response
          JR    NC,BADC          ; If greater than allowed error
EDOK      DEC    HL              ; Move response down one
          ADD   HL,HL            ; Double HL
          PUSH  HL               ; Save it
          ADD   HL,HL            ; Row count x 4
          POP   BC               ; BC = row count x 2

```

```

ADD      HL,BC      ; HL = Row count x 6
LD       BC,ARST   ; Get store start address
ADD      HL,BC      ; Add row offset
PUSH     HL         ; Save resulting pointer
LD       HL,MOTNS  ; Print
CALL     PSTR      ; Motor number string
CALL     GINT      ; Get Answer
JR       NZ,BADNM  ; Bad answer
LD       A,H       ;
OR       A         ;
JR       NZ,BADNM  ; Response too large
LD       A,L       ;
CP       1         ;
JR       C,BADUM   ; No motor number < 1
CP       7         ;
JR       NC,BADNM  ; No motor number > 6
POP      HL        ; Restore = Memory pointer
DEC      A         ; Motor offset 0 -> 5
LD       C,A       ;
LD       B,0       ; Add to memory pointer
ADD      HL,BC     ; Now we point to motor in store
PUSH     HL        ; Save pointer
LD       HL,NVALS  ;
CALL     PSTR      ; Print new step value
CALL     GINT      ; Get response
JR       NZ,BADNM  ; Bad answer
LD       A,H       ;
CP       0FFH     ;
JR       NZ,PEDIT  ; We have a positive response
BIT      7,L       ; New negative step value too
JR       Z,BADNM   ; large
JR       MOTAS     ; Step value OK
PEDIT   OR         A ; New positive step value too
JR       NZ,BADNM  ; large
BIT      7,L       ; so exit
JR       NZ,BADNM  ; else ok
MOTAS   LD         A,L ; Get step value
POP      HL        ; Restore memory pointer
LD       (HL),A    ; Place step value in store
JP       QUES1     ; Go do next operation
BADNM   POP        HL ;
BADC    LD         HL,BADMS ; Print error message and
CALL     PSTR      ;
JP       QUES1     ; return to main loop

```

READ ROUTINE

```

; Reads stored sequence from cassette
; into memory

READ    LD      HL,CASRD    ; Point to wait message
        CALL   PSTR        ; Print it
        CALL   GCHRA       ; Get response
        CALL   PNEWL       ; Print new line
        CP     '.'         ; Is response a dot?
        JP     Z,QUES1     ; Yes then exit
        CP     SPAC        ; Is it a space?
        JR     NZ,READ     ; No then try again
        XOR    A           ; Clear A=Drive zero
        CALL   CASON       ; Switch on drive zero
        CALL   DELS        ; Short delay
        CALL   RDHDR       ; Read header from tape
        CALL   READC       ; Read first character
        LD     B,A         ; Put in B
        CALL   READC       ; Read second character
        LD     C,A         ; Place in C
        OR     B           ; BC now equals count
        JP     Z,NOSTR     ; Count zero, so exit
        LD     (COUNT),BC ; Set count = read count
        LD     HL,ARST     ; Point to start of store
ROWNR   PUSH   BC         ; Same count
        LD     E,0         ; E = Check sum for a row
        LD     B,6         ; B = Column Count
RDBYT   CALL   READC       ; Read a row element
        LD     (HL),A      ; Store it
        ADD   A,E         ; Add it to check sum
        LD     E,A         ; Store in check sum
        INC   HL          ; Inc memory pointer
        DJNZ RDBYT       ; Do next element
        POP   BC         ; Restore row count
        CALL   READC       ; Read check digit
        CP     E          ; Same as calculated?
        JR     NZ,RDERR   ; No then error
        DEC   BC         ; Decrement row count
        LD     A,B        ; See if row count
        OR    C           ; is zero
        JR     NZ,ROWNR   ; No then read next row
        CALL   CASOF       ; Switch cassette off
        JP    TAPEF       ; exit
RDERR   LD     HL,RDMSG    ; Error message for tape
        CALL   PSTR        ; Print it
        JP    QUES1       ; Go to main loop

```

WRITE ROUTINE

; Writes a stored sequence to tape

```

WRITE      LD      BC,(COUNT)  ; Get row count
           LD      A,B          ;
           OR      C            ;
BADWI      JP      Z,NOSTR      ; If zero exit
           LD      HL,CASRD     ; print message
           CALL   PSTR         ;
           CALL   GCHRA        ; Get answer
           CALL   PNEWL        ; Print new line
           CP     '.'          ; Is answer a dot
           JP     Z,QUES1      ; Yes then exit
           CP     SPAC         ; Is answer a space
           JR     NZ,BADWI     ; No then try again
           XOR    A            ; Clear drive number
           CALL   CASON        ; Switch on drive zero
           CALL   DELT         ; delay
           CALL   WRLDR        ; Write Leader
           CALL   DELT         ; delay
           LD     BC,(COUNT)  ; Get count into BC
           LD     A,B          ;
           CALL   WRBYA        ; Write higher byte
           LD     A,C          ; Get lower byte of count into A
           CALL   DELT         ; delay
           CALL   WRBYA        ; Write lower byte
           LD     HL,ARST      ; Point to start of sequence of store
ROWNW      PUSH   BC          ; Save row count
           LD     E,0          ; Clear check sum
           LD     B,6          ; Six motor slots per row
WRBYT      LD     A,(HL)       ; Get motor slot N
           CALL   DELS         ; delay
           CALL   WRBYA        ; Write it
           CALL   DELS         ; delay
           ADD    A,E          ; add to check sum
           LD     E,A          ;
           INC    HL           ; Inc memory pointer
           DJNZ  WRBYT        ; Do for all six motors
           CALL   WRBYA        ; Write check sum
           POP    BC          ; Restore row count
           DEC    BC          ; Decrement row count
           LD     A,B          ;
           OR     C            ; Test if zero
           JR     NZ,ROWNW     ; No then try again
           CALL   CASOF        ; Switch cassette off
           JP     QUES1        ; Back to main loop

```

CHECK ROUTINE

; Checks tape with sequence in store

```

CHECK      LD      BC,(COUNT)    ; Get row count
           LD      A,B            ;
           OR      C              ;
           JP      Z,NOSTR        ; If zero exit
BADCI      LD      HL,CASRD       ; Print wait message
           CALL   PSTR           ;
           CALL   GCHRA          ; Get answer
           CALL   PNEWL          ; Print new line
           CP     '.'            ; is response a '.'
           JP      Z,QUES1       ; Yes then go to main loop
           CP     SPAC           ; Is it a space
           JR     NZ,BADCI       ; No then try again
           XOR    A              ; Clear cassette number
           CALL   CASON          ; Switch drive zero on
           CALL   RDHDR          ; Read header from tape
           LD     BC,(COUNT)    ; Get row count
           CALL   READC          ; Read first section
           CP     B              ; Same?
           JR     NZ,RDERR       ; No then error
           CALL   READC          ; Read lower byte of count
           CP     C              ; Same?
           JR     NZ,RDERR       ; No then error
           OR     B              ; Zero count from tape
           JP     Z,NOSTR        ; So exit
           LD     HL,ARST        ; Point to start of memory
ROWNC      PUSH   BC             ; Save count
           LD     E,0            ; Check sum is zero
           LD     B,6            ; Count is 6
CKBYT      CALL   READC          ; Read a motor step element
           CP     (HL)           ; Same as in store?
           JP     NZ,RDERR       ; Not the same so error
           ADD   A,E            ;
           LD     E,A            ; Add to check sum
           INC   HL              ; Advance memory pointer
           DJNZ  CKBYT          ; Do next row element
           POP   BC             ; Restore row count
           CALL   READC          ; Read check sum
           CP     E              ; Same as check sum calculated
           JP     NZ,RDERR       ; No then error
           DEC   BC             ; Decrement count
           LD     A,B            ;
           OR     C              ; Is count zero?
           JP     NZ,ROWNC       ; No then do next row
           CALL   CASOF          ; Switch cassette off
TAPEF      LD     HL,TAPOK       ; Print tape off message
           CALL   PSTR           ;
           JP     QUES1          ; and back to main loop

```

BOOT AND FINISH COMMANDS

; This routine restarts the program

```

BOOT      LD      HL,BOOTS      ; Print "DO YOU REALLY
          CALL    PSTR          ; WANT TO RESTART?"
          CALL    GCHRA         ; Get answer
          CP      'Y'          ; user typed 'Y'?
          JP      Z,STARM       ; Yes then restart program
          CP      'N'          ; No 'N'?
          JR      NZ,BOOT       ; Then try again
          CALL    PNEWL         ; else print new line and
          JP      QUES1         ; back to main loop

```

; This is the exit from program Section to TRS80
; system level

```

FINSH     LD      HL,RELYQ      ; Print "REALLY QUIT"
          CALL    PSTR          ;
          CALL    GCHRA         ; Get answer
          CP      'Y'          ; User typed a 'Y'
          JR      NZ,TRYNO      ; No then try 'N'
          LD      HL,SIGOF      ; Print ending message
          CALL    PSTR          ; and then
          JF      FINAD         ; return to TRS80 System
TRYNO     CP      'N'          ; User typed an 'N'
          JR      NZ,FINSH      ; No then try again
          CALL    PNEWL         ; Print a new line
          JP      QUES1         ; Back to main loop

```

OTHER SHORT COMMANDS

```
; SETAM  clears arm position array

SETAM    CALL    RESET    ; Clear Arm array  (POSAR)
         JP      QUES1    ; Back to main loop

; TOSTM  moves the arm back to its start position

TCSTM    CALL    MOVTO    ; Steps motors till POSAR elements
         JP      QUES1    ; are zero then back to main loop

; FREARM  frees all motors for user to move arm
; by hand

FREARM   CALL    CLRMT    ; Output all ones to motors
         JP      QUES1    ; and now to main loop

; MANU  allows the user to move the arm using
; the 1-6 keys and the 'Q' 'W' 'E' 'R' 'T' 'Y' keys
; The movements made are not stored.

MANU     LD      A,1      ; Set in manual mode for the
         LD      (MAN),A ; keyin routine
MANUA    CALL    KEYIN    ; Now get keys and move motors
         JP      NZ,MANUA; If non zero then move to be done
         XOR     A        ; Clear manual flag
         LD      (MAN),A ;
         JP      QUES1    ; Back to main loop
```

THE GO COMMAND

```

; This command causes the computer to step
; through a stored sequence and makes the arm
; follow the steps stored, if the sequence is to
; be done forever then the arm resets itself at
; the end of each cycle.

GO      CALL      PNEWL      ; Print a new line
        CALL      MOVTO     ; Move arm to start.
        XOR       A         ; Clear
        LD        (FORFG),A ; Forever Flag FORFG
        LD        HL,AORNM  ; Print "DO ONCE OR FOREVER
        CALL      PSTR      ; Message
        CALL      GCHRA     ; Get answer and print it
        CALL      PNEWL     ; Print a new line
        CP        '0'      ; User typed an '0'
        JR        Z,ONECY   ; Do sequence till end
        CP        'F'      ; User typed an 'F'
        JR        NZ,GO     ; No then re-try
        LD        A,1       ; Set forever flag
        LD        (FORFG),A ; to 1
ONECY   LD        A, '.'    ; Print a '.'
        CALL      PUTCHR    ; Using PUTCHR
        CALL      DOALL     ; Execute the sequence
        LD        A,(FORFG) ; Test FORFG, if zero
        OR        A         ; then we do not want
        JP        Z,NORET   ; to carry on so exit
        CALL      DELT      ; delay
        CALL      MOVTO     ; Move arm to start
        CALL      DELLN    ; Delay approx 1 second
        JR        ONECY    ; Do next sequence
NORET   LD        HL,DONMS  ; Print sequence done
        CALL      PSTR      ;
        JP        QUES1    ; and go to main loop

```

THE DISPLAY COMMAND

```
; This command allows the user to display
; the motor sequence so that he can then
; alter the contents of a sequence by using
; the Edit command
```

```
DISP      LD      HL,DISPS      ; Point to header string
          CALL    PSTR          ; and display it
          CALL    POSDS        ; Print out the relative position
          LD      HL,ARST      ; Point to sequence start
          LD      BC, (COUNT) ; BC = how many rows to print
          LD      A,B          ;
          CR      C            ; Test if count is zero
          JP      NZ,SETBC     ; No then jump to rest of
NOSTR     LD      HL,NODIS     ; display else print message
          CALL    PSTR          ; telling user no display and
          JP      QUES1        ; return to the main loop
SETBC     LD      EC,000       ; Clear BC for row count
DOROW    PUSH    BC            ; Save it
          PUSH    HL            ; Save memory position
          LD      H,B          ;
          LD      L,C          ; HL = row count
          INC     HL            ; Now row count =N+1
          LC      1X,NUMAR     ; 1X points to buffer fcr ASCII String
          CALL    CBTAS        ; Convert HL to ASCII
          LD      HL,NUMAR     ; Point to ASCII string
          CALL    PSTR          ; now print it
          LD      A, '.'       ;
          CALL    PUTCHR        ; Print a '.'
          POP     HL            ; Restore memory pointer
          LD      B,6          ; Motor count to B (6 motors)
NEXTE    LD      A,(HL)       ; Get step value
          PUSH    HL            ; Save memory pointer
          PUSH    BC            ; Save motor count
          BIT     7,A          ; Test bit 7 of A for sign
          JP      Z,NUMPO      ; If bit = 0 then positive step
          LD      H,0FFH       ; Make B = negative number
          JR      EVAL         ; Do rest
NUMPO    LD      H,0          ; Clear H for positive number
EVAL     LD      L,A          ; Get low order byte into L
          LD      1X,NUMAR     ; Point to result string
          CALL    CBTAS        ; Call conversion routine
          LD      PL,NUMAR     ; HL points to result
          CALL    PSTR          ; Print resulting conversion
          LD      A,(3810H)    ; Get keyboard memory location
          BIT     0,A          ; Test for zero key pressed
          JR      Z,NOSTP      ; Not pressed, then skip
DOSTF    CALL    GCER         ; Wait till next character entered
          CP      '.'         ; Is it a dot?
          JR      NZ,NOSTP     ; No then carry on
          CALL    PNEWI        ; else print a new line
          POP     BC            ; and restore all the registers
          POP     HL            ; and the stack level
```

	POP	BC	;
	JP	QUES1	; Jump back to main loop
NOSTP	POP	BC	; Restore column count
	POP	HL	; Restore memory pointer
	INC	HL	; Increment memory pointer
	CALL	PSPAC	; Print a space between
			; numbers
	DJNZ	NEXTE	; Do for six motors
	CALL	PNEWL	; Print a new line
	POP	BC	; Restore row count
	INC	BC	; Increment row count
	LD	A,(COUNT)	; Get lower count byte
	CP	C *	; Is it the same
	JR	NZ,DOROW	; No then do next row
	LD	A,(COUNT+1)	; Get higher order count byte
	CP	B	; Same?
	JR	NZ,DOROW	; No then do next row else
	CALL	PNEWL	; print a new line and then
	JP	QUES1	; back to main loop

INDEX

SECTION 3

.....Execute a control program

.....Driver all motors direct

.....Set up system

.....Use POBAB to test system

.....Handover and back

STurn on off motors

UTurn off all motors

BReset CPDS all ways to

RDrive directed motors

OStop motors via DMAT

UDelay on direction chan

TUpdate TRUP array during

IScan keyboard and build

NConvert to bit 2's comp

EClear NOTBE array

SGet 16 bit signed value

.....Display relative position

.....Increment relative post

SUBROUTINES INDEX

DOALL Execute a stored sequence once
DRIVL Drives all motors directed by TBUF
INIT Set up system
MOVTC Use POSAR to rest system arm
TORQUE Turn on off motors
CLRMT Turn off all motors
SETDT Reset CTPOS elements to one
DRAMT Drive directed motors
STEPM Step motors via DRAMT
DNEWD Delay on direction change
SRAMT Update TBUF array during learn
KEYIN Scan keyboard and build up motors to move
CBTAS Convert 16 bit 2's complement number to ASCII
CLRME Clear MOTBF array
CTBUF Clear TBUF, DRBUF & MOTBF arrays
GINT Get 16 bit signed value from keyboard
POSDS Display relative position array elements
POSIC Increment relative position array elements
STORE Copy TBUF to current ARST slice
RESET Clear POSAR array
PUTCHR Print a character
PSTR Print a string
PSPAC Print a space
PNEWL Print a carriage return

SUBROUTINES INDEX (continued)

SCKBD.....Scan the keyboard
GCHRA.....Get a character and print it
CLRSC.....Clear the Screen
DELSW.....Delay on value in B
DELS.....Delay approx 0.001 sec
DELT.....Delay approx 0.01 sec
DELLN.....Delay approx 1.0 sec

SUBROUTINE DOALL

; This subroutine executes a sequence in store once.
 ; Forever flag FORFG is cleared if user types a '.'

```

DOALL      LD      BC,(COUNT)      ; Get sequence row count
           LD      A,B              ;
           OR      C                ; If count zero then
           JR      Z,RET2           ; exit
           LD      HL,ARST          ; HL points to memory start
NMOTS      LD      DE,TBUF          ; DE points to temporary buffer
           PUSH   BC                ; Save count
           LD      BC,0006          ; Motor count of six
           LDIR   ; Copy memory slice into TBUF
           PUSH   HL                ; Save new memory pointer
           CALL   DRIVL             ; Drive all motors fcr this slice
           CALL   SCKBD             ; See if keyboard input
           POP    HL                ; Restore memory pointer
           POP    BC                ; Restore row count
           CALL   DNEW              ;
           CP     '.'               ; User typed a '.'
           JR      NZ,CARON         ; No then continue
RET2       XOR    A                 ; Clear A
           LD     (FORFG),A         ; Clear flag to halt routine above
           RET    ; exit
CARON     DEC    BC                ; Decrement count
           LD     A,B              ;
           OR     C                 ; Test for zero
           JR     NZ,NMOTS          ; No then carry on else
           RET    ; return
  
```

SUBROUTINE DRIVL

; This routine is given TBUF, it then drives all
 ; the motors that need to be driven, till TBUF = 0

```

DRIVL      LD      C,0          ;
SCANW      LD      B,6          ; Set BC = motor count
           LD      HL,TBUF      ; Point to TBUF
TBZER      LD      A,(HL)       ; Get step value from TBUF
           OR      A            ; Is it zero?
           JR      NZ,TBNZR     ; No then continue
           INC     HL           ; Point to next TBUF location
           DJNZ   TBZER        ; Do next motor check
           RET                    ; If no motor to step, then return
TBNZR      LD      DE,MOTBF + 5 ; DE points to last direction array
           LD      HL,TBUF + 5 ; HL points to TBUF
           LD      B,6          ; B = motor count
DOAGN      LD      A,(HL)       ; Get motor step value
           CP      0            ; Is it zero?
           JR      Z,NOEL       ; Yes then skip
           JP      M,SNEG       ; Is it negative ie, reverse
SPOS       LD      A,3          ; No positive, so load MOTBF (N)
           LD      (DE),A       ; With 3
           DEC     (HL)         ; Decrement motor count in TBUF
           JR      NOFIL        ; Complete the MOTBF array
SNEG       LD      A,1          ; Set MOTBF = 1 for
           LD      (DE),A       ; a positive drive
           INC     (BL)         ; Decrement negative count
           JR      NOFIL        ; Do rest of MOTBF
NOEL       XOR     A            ; Clear MOTBF (N)
           LD      (DE),A       ;
NOFIL      DEC     DE           ; Move to next MOTBF element
           DEC     HL           ; Move to next TBUF element
           DJNZ   DOAGN        ; Do for all six motors
           LD      A,1          ;
           LD      (KEYP),A     ; Set key pressed flag
           CALL   STEPM        ; Step all motors once if
           DEC     C            ; any to step
           JF     NZ,SCANW     ; Do for maximum of 128 cycles
           RET                    ; then return
  
```

SUBROUTINE INIT

; INIT clears the row count (COUNT), resets the
; MAN flag, clears the TBUF, DRBUF, & MOTBF arrays
; The CUROW pointer is reset to the start of the ARST,
; position array is cleared.

```
INIT      LD      HL,0          ; Set HL = 0
          LD      (COUNT),HL  ; and clear the row count
          XOR     A             ; Clear A
          LD      (MAN),A      ; Now clear MAN
          LD      HL,ARST      ; HL = start of arm store
          LD      (CURCW),HL   ; CUROW = start of arm store
          CALL    CTBUF        ; Clear TBUF, DRBUF & MOTBF
          CALL    RESET        ; Clear the POSAR array
          CALL    CLRMT        ; Free all motors
          RET                    ; EXIT
```

SUBROUTINE MOVTO

; This routine takes the POSAR array and uses it to drive
 ; all the motors until the ARM is in its defined start position

```

MOVTO    PUSH    AF          ; *
         PUSH    BC          ; *
         PUSH    DE          ; *   Save registers
         PUSH    HL          ; *
RES1     ID      HL,POSAR    ; HL points to POSAR
         LD      B,12        ; B = count of 12
NRES1    LD      A,(HL)      ; Get POSAR element
         CR      A           ; Is it zero?
         JR      NZ,MTSA     ; No then continue
         INC     HL          ; Point to next POSAR element
         DJNZ   NRES1        ; See if all zero
         JR      ENDSC       ; All zero so end:
MTSA     LD      HL,POSAR+10 ; HL points to POSAR
         LP     DE,MOTBF+    5 ; DE points to MOTBF
         LE     B,6          ; B = count
RSCAN    PUSH    BC          ; Save count
         LD      C,(HL)      ; Get lower byte
         INC     HL          ; Advance HL pointer
         LD      B,(HL)      ; Get high byte of POSAR element
         LD      A,C         ; Get low byte into A
         OR      B           ; See if POSAR(N) is zero
         JP      NZ,DOMPL    ; no skip
         LD      (DE),A      ; Zero MOTBF (N)
         DEC     HL          ; advance POSAR pointer
         JR      NMDR        ; Do next motor
DOMPL    LD      A,B         ; See direction to move in
         BIT    7,A          ;
         JR      Z,RMOT1     ; Go in reverse
         INC     BC          ; Go forward
         LD      A,1         ; A = forward
         JR      DOIT1       ; Do rest
RMOT1    DEC     BC          ; Dec count for reverse
         LD      A,3         ; Set reverse in A
DOIT1    LD      (DE),A      ; Store reverse in MOTBF (N)
         LD      (HL),B      ; Store updated POSAR count
         DEC     HL          ; in POSAR (N)
         LD      (HL),C      ; Store lower byte
NMDR     DEC     HL          ;
         DEC     HL          ; point to next POSAR element
         DEC     DE          ; Move to next MOTBF element
         POP     BC          ; Restore motor count
         DJNZ   RSCAN        ; Do for next motor
         CALL   DRAMT        ; Drive all motors to be driven
         JR      RES1        ; Do till all POSAR slots zero
ENDSC    POP     HL          ; *
         POP     DE          ; *
         POP     BC          ; *   Restore all registers
         POP     AF          ; *
         RET                    ; Return

```

SUBROUTINES TORQUE, CLRMT AND SETDT

```
; TORQUE switches of motors on and sets CTPOS(N)'s
; CLRMT turns all motors off and sets CTPOS(1-6)
; SETDT sets all CTPOS elements to start offset
; position which equals 1.
```

```
TORQUE    PUSH    AF      ; * Set clear motor-
          PUSH    BC      ; *
          PUSH    DE      ; * Save Registers
          PUSH    HL      ; *
          LD      HL,TORMS ; Print TORQUE ON message
          CALL    PSTR     ;
          LD      DE,CTPOS ; Point to FTABL offset array
          LD      HL,MOTBF ; Point to last drive table
          LD      B,6      ; B = motor count
TORQ1     LD      A,(HL)   ; Get motor value
          OR      A        ; Is it zero?
          JR      NZ,TORQ2 ; No then skip
          LD      A,1      ; Reset CTPOS(N) to position 1
          LD      (DE),A   ; in FTABL
          LD      A,B      ; Get motor address in A
          SLA     A        ; Shift it left for interface defn
          OR      192      ; or in FTABL pulse
          OUT     (PORT),A ; Output it to selected motor
TORQ2     INC     DE      ; Advance points to next
          INC     HL      ; motors
          DJNZ   TORQ1    ; Do next motor
          JR      TOQCL   ; Exit with register restoration
CLRMT     PUSH    AF      ; * clear all motors torque
          PUSH    BC      ; *
          PUSH    DE      ; * Save Registers
          PUSH    HL      ; *
          LD      HL,NOTOR ; Print "NO TORQUE" message
          CALL    PSTR     ;
          LD      D,0F0H   ; Pattern for motors off
OTMT      LD      B,6      ; B = Motor count
CLNT      LD      A,B      ; Get motor address in A
          SLA     A        ; Shift into correct bit position
          OR      D        ; Combine with coils off pattern
          OUT     (PORT),A ; Output to selected motor
          DJNZ   CLMT     ; Do next motor
          CALL    SETDT   ; Clear CTPOS array to value of 1
TOQCL     POP     HL      ; *
          POP     DE      ; *
          POP     BC      ; * Restore Registers
          POP     AF      ; *
          RET            ; Done, exit
```

```

SETDT      PUSH    BC      ; * Set CTPOS elements to start
           PUSH    DE      ; * Save used registers
           PUSH    HL      ; *
           LD      B,6      ; Motor count to B
           LD      HL,CTPOS ; HL points to CTPOS array
NSET1     LD      (HL),1    ; Set CTPOS(N) to start position = 1
           INC     HL      ; Increment HL
           DJNZ   NSET1    ; Do set up next CTPOS element
           POP     HL      ; *
           POP     DE      ; * Restore used registers
           POP     BC      ; *
           RET      ;

```

SUBROUTINE DRAMT

; DRAMT drives all six motors directly and uses
 ; FTABL to output the correct pulse patterns.
 ; For half stepping the pattern must be changed in FTABL
 ; and the bounds in DRAMT

```

DRAMT      PUSH      AF          ; *
           PUSH      BC          ; *
           PUSH      DE          ; *   Save Registers
           PUSH      HL          ; *
           LD        B,6          ; B = motor count
           LD        DE,MOTBF +5 ; Point to MOTBF array
           LD        HL,CTPOS     ; HL points to FTABL offset array
NMTDT      LD        A,(DE)      ; Get MOTBF(N)
           OR        A           ; Is it zero?
           JR        Z,IGMTN     ; If zero; then skip
           BIT       1,A         ; Test direction
           CALL      OUTAM       ; Step motor
           JR        Z,REVMT     ; If direction negative then jump
           INC       A           ; Increment table counter
           CP        5           ; Upper bound?
           JR        C,NORST     ; No then continue
           LD        A,1         ; Reset table offset
NORST      LD        (HL),A      ; Store in CTPOS (N)
IGMTN      INC       HL          ; Increment CTPOS pointer
           DEC       DB          ; Decrement MOTBF pointer
           DJNZ     NMTDT       ; Do for next motor
           CALL      DELT        ; Delay after all pulses out
           CALL      DELS        ; *
           POP       HL          ; *
           POP       DE          ; *
           POP       BC          ; *   Restore Registers
           POP       AF          ; *
           RET              ; Exit
REVMT      DEC       A           ; Move table pointer on
           CP        1           ; Compare with lower bound
           JR        NC,NORST    ; If no overflow then continue
           LD        A,4         ; Reset table offset
           JR        NORST       ; Do next motor
OUTAM      LD        A,(HL)      ; Get table offset 1-4
           PUSH      AF          ; *
           PUSH      DE          ; *   Save Registers
           PUSH      HL          ; *
           LD        HL,FTABL-1 ; Get table start
           LD        D,0         ;
           LD        E,A         ; DE now equals 1-4
           ADD       HL,DE       ; Add to FTABL -1 to get address
           LD        A,(HL)      ; Get motor pulse pattern
           LD        C,B         ; Get address field in C and
           SLA      C           ; shift it one to the left
           OR        C           ; or in the pulse pattern
           OUT      (PORT),A    ; Output to interface circuitry
           POP       HL          ; *
           POP       DE          ; *   Restore Registers
           POP       AF          ; *
           RET              ; Return

```

SUBROUTINE STEPM

; This routine causes all motors that should be
 ; stepped to be so, and updates the motors relative
 ; positions from their start positions.

```

STEPM      PUSH  AF          ; *
           PUSH  HL          ; * Save Register
           PUSH  BC          ; *
           LD    HL,MOTBF    ; HL points to motor buffer
           LD    B,6         ; B = Count
TRY0       LD    A,(HL)      ; Get motor value 3 or 1
           OR    A           ; Zero?
           JR    NZ,CONTA    ; No then continue
CONT       INC   HL          ; Point to next motor
           DJNZ TRY0         ; Do next motor
           POP   BC          ; *
           POP   HL          ; * Restore Registers
           POP   AF          ; *
           RET              ; Exit
CONTA     POP   BC          ; *
           POP   HL          ; * Restore registers
           CALL  DRAMT       ; Drive motors
           CALL  POSIC       ; Increment relative position
           POP   AF          ; * Restore AF
           RET              ; Exit
  
```

SUBROUTINE DNEWD

; This subroutine checks to see if any motors are
 ; changing direction , if so a delay is inserted
 ; into the sequence.

```

DNEWD  PUSH  AF          ; *
        PUSH  BC          ; *
        PUSH  DE          ; * save used registers
        PUSH  HL          ; *
        LD   BC,6         ; Load BC with count
        OR   A            ; Clear carry
        SBC  HL,BC       ; HC points to previous motor slice
        LD   D,H         ;
        LD   E,L         ; Move HL to DE
        POP  HL          ; Restore current row pointer
        PUSH HL          ; Save again
        LD   B,C         ;
NCOMP  LD   A,(HL)       ; Get contents of this row
        CP   0           ; See if positive or negative
        LD   A,(DE)      ; Get identical previous motor slot
        JP   P,PDIR     ; if positive do for positive motor
NDIR   CP   0           ; Compare if both in same
        JP   M,NXTCK    ; direction then skip else
CDDEL  CALL  DELLN      ; delay and
NCDSG  POP  HL          ; *
        POP  DE          ; *
        POP  BC          ; * Restore registers
        POP  AF          ; *
        RET             ; Now return
PDIR   CP   0           ; If previous motor is negative
        JP   P,NXTCK    ; then delay, else do for next
        JR   CDDEL      ; motor slot
NXTCK  INC  HL          ; increment current row pointer
        INC  DE          ; increment lost row pointer
        DJNZ NCOMP      ; do for next motor
        JR   NCDSG      ; Return with no large (1 sec) delay
  
```

SUBROUTINE SRAMT

```

; SRAMT is responsible for updating the TBUF
; elements and for setting the STRFG if a situation
; exists where the TBUF array should be stored in the
; current ARST slot. This will occur if any motor changes
; direction or a motor exceeds the allowed slot
; boundary of -128 to 127.

```

```

SRAMT      LD      A,(MAN)      ; Get manual flag
           OR      A            ; Is it zero?
           JP      NZ,STEPM     ; Yes then just step motors
           LD      (STRFG),A    ; Clear the store flag
           LD      B,6          ; B = motor count
           LD      1X,DRBUF+6   ; 1X = previous direction buffer
           LD      1Y,MOTBF+6   ; 1Y = current buffer
           LD      HL,TBUF +6   ; HL = step buffer
NTMOT      DEC     1Y           ;
           DEC     1X           ;
           DEC     HL           ; move pointers
           LD      A,(1Y+0)     ; Get current motor direction
           OR      A            ; No work to do
           JR      Z,NODRV      ; skip, if so
           CP      1            ; Reverse
           JR      Z,REVDR      ; Yes then skip
FORDR      LD      A,(1X+0)     ; Get previous direction
           CP      1            ; Direction change?
           JR      NZ,CFORD     ; No then advance TBUF(N) step
           CALL    SETST        ; Set the store flag
           LD      (1Y+0),0     ; Clear MOTBF element.
           JR      NODRV        ; Do next motor
CFORD      INC     (HL)         ; Increment motor step in TBUF
           LD      A,(HL)       ; Get new value
           CP      127          ; Check against upper board
           CALL    SETST        ; Limit reached then store flag
           LD      (1X+0),3     ; Set previous direction
NODRV      DJNZ   NTMOT         ; Do next motor
           CALL    STEPM        ; Step motors to be driven
           LD      A,(STRFG)    ; Examine store flag
           OR      A            ; Zero?
           JP      NZ,STORE     ; No then do store operation
           RET                  ; Exit
REVDR      LD      A,(1X+0)     ; Get previous direction
           CP      3            ; Direction reversed?
           JR      NZ,CREV1     ; No then continue
           CALL    SETST        ; Else set store TBUF in ARST flag
           LD      (1Y+0),0     ; clear MOTBF element
           JR      NODRV        ; Do next motor
CREV1      DEC     (HL)         ; Advance step count in TBUF (N)
           LD      A,(HL)       ; Get element
           CP      -128         ; Compare with upper negative bound
           CALL    Z,SETST      ; Limit reached so set store flag
CREVD      LD      (1X+0),1     ; Set Direction
           JR      NODRV        ; Do next motor
SETST      PUSH   AF           ; Save AF
           LD      A,1          ; Set store flag STRFG
SETSC      LD      (STRFG),A    ; to one
           POP    AF           ; Restore AF
           RET                  ; Continue

```

SUBROUTINE KEYIN

```

; This routine scans the keyboard checking for
; the keys '1-6' and 'Q''W''E''R''T''Y' and 'S'
; and 0. It then drives the motors corresponding
; to the keys pressed. If in learn mode the
; sequence is started.

KEYIN      CALL      CLRMF      ; Clear MOTBF array
           LD        A,(3840H)  ; Get TRS80 keyboard byte
           BIT       7,A        ; See if
           JR        Z,IGDEL    ; No space key so skip
           CALL      DELT       ; *
           CALL      DELT       ; * Slow motor driving
IGDEL      XOR       A          ; Clear KEY PRESSED flag
           LD        (KEYP),A   ;
           LD        A,(3810H)  ;
           BIT       0,A        ; Is the zero key pressed?
           JR        Z,TRYS     ; No then skip
           JP        NOTNG      ; Go to do nothing
TRYS       LD        A,(3804H)  ; See if
           BIT       3,A        ; 'S' key pressed
           LD        A,(3810H)  ; Restore memory value
           JR        Z,TRYN1    ; No then skip
           LD        A,(MAN)    ; See if in manual mode
           CR        A          ;
           CALL      Z,STORE    ; No then store TBUF
           OR        1          ; Set not finished flag
           RET        ; and exit to caller
TRYN1      LD        BC,0       ; Clear MOTBF offset in BC
           BIT       1,A        ; See if '1' key is pressed
           JP        Z,TRYN2    ; No then skip else
           CALL      FORMT      ; Set up motor 1 position in MOTBF
TRYN2      INC       BC         ; Increment MOTBF offset
           BIT       2,A        ; See if '2' key pressed
           JP        Z,TRYN3    ; No skip
           CALL      FORMT      ; Set second motor forward
TRYN3      INC       BC         ; Advance offset
           BIT       3,A        ;
           JP        Z,TRYN4    ; See if '3' key pressed, No skip
           CALL      FORMT      ; Set forward direction on Motor 3
TRYN4      INC       BC         ; Increment offset in BC
           BIT       4,A        ; See if key '4' is pressed
           JP        Z,TRYN5    ; No then test key '5'
           CALL      FORMT      ; Do forward direction for Motor 4
TRYN5      INC       BC         ; Advance offset
           BIT       5,A        ; Key '5' pressed
           JP        Z,TRYN6    ; No skip
           CALL      FORMT      ; Do set up for motor 5
TRYN6      INC       BC         ; Advance offset
           BIT       6,A        ; Key '6' pressed
           JP        Z,TRYQT    ; No then try 'Q'
           CALL      FORMT      ; Do for motor 6

```

```

TRYQT      LD      BC,0          ; Clear BC offset for motor 1
           LD      A,(3804H)    ; See if 'Q' key pressed
TRYQ       BIT      1,A         ;
           JP      Z,TRYW       ; No then skip
           CALL    BACMT        ; Set motor 1 for backward
TRYW       INC      BC          ; Advance pointer
           BIT      7,A         ; See if 'W' key pressed
           JP      Z,TYRE       ; No skip
           CALL    BACMT        ; Do backward for motor 2
TRYE       INC      BC          ; Advance pointer offset
           LD      A,(3801H)    ; See if
           BIT      5,A         ; 'E' key pressed
           JR      Z,TRYR       ; No skip
           CALL    BACMT        ; Set motor 3 for backward
TRYR       INC      BC          ; Advance pointer offset
           LD      A,(3804H)    ; See if
           BIT      2,A         ; Key 'R' is pressed
           JP      TRYT         ; No skip
           CALL    BACMT        ; Set motor 4 backward
TRYT       INC      BC          ; Advance offset
           BIT      4,A         ; Is key 'T' pressed?
           JP      Z,TRY       ; No skip
           CALL    BACMT        ; Set motor 5 backward
TRY       LD      A,(3808H)    ; Is the 'Y' key pressed?
           INC      BC          ; Advance offset
           BIT      1,A         ; No key
           JP      Z,SOMEN      ; 'Y' then skip
           CALL    BACMT        ; Set motor 6 for backward
SOMEN      CALL    SRAMT        ; Step motors, maybe store.
           OR      1           ; Set zero key not pressed flag
           RET              ; Return to caller
NOTNG      LD      A,(MAN)     ; Zero was pressed so see
           OR      A           ; if in learn mode
           CALL    Z,STORE     ; Yes then store
           XOR     A           ; Set zero flag and
           RET              ; Return to caller
FORMT      LD      E,3         ; Set for forward direction
           JP      SETMT       ; Do set motor slot in MOTBF
BACMT      LD      E,1         ; Set for reverse direction
SETMT      LD      HL,MOTBF    ; Point to MOTBF
           ADD     HL,BC        ; Add in motor offset
           PUSH    AF          ; Save AF
           LD      A,(HL)      ; Get byte
           OR      A           ; See if zero
           JR      Z,DOMOT     ; Yes then set byte
           XOR     A           ; Clear
           LD      (HL),A      ; byte in MOTBF user wants both
           POP     AF          ; directions clear byte
           RET              ; Restore AF and return
DOMOT      LD      (HL),E      ; Set byte in MOTBF
           LD      A,1         ; and set
           LD      (KEYP),A    ; key pressed flag
           POP     AF          ; Restore AF
           RET              ; exit from routine

```

SUBROUTINE CBTAS

; This subroutine makes a signed binary value in
 ; HL into arm ASCII String and stores the string
 ; in the locations pointed to by 1X

```

CBTAS    PUSH    AF          ; *
         PUSH    HL          ; *
         PUSH    DE          ; *   Save Registers
         PUSH    1X         ; *
         BIT     7,H         ; Test sign of number
         JR     Z,POSNO     ; If zero then positive number
         LD     A,H         ;
         CPL                    ; Complement number if negative
         LD     H,A         ;
         LD     A,L         ;
         CPL                    ;
         LD     L,A         ;
         INC    HL          ; Now 2's complement negative
         LD     A,MINUS     ; Place minus sign in string
PUTSN    LD     (1X+0),A    ; Pointed to by 1X
         INC    1X         ; Advance 1X pointer
         JR     CONUM       ; Do rest of conversion
POSNO    LD     A,SPAC     ; Place a space if number positive
         JR     PUTSN      ; Jump to copy space to memory
CONUM    PUSH    1Y         ; Save 1Y register
         LD     1Y,BTOAT   ; Point to subtraction table
NUMLP    LD     A,NUMBA     ; Get ASCII 0 in A
         LD     E,(1Y+0)   ;
         LD     D,(1Y+1)   ; Get table value
SUBBA    OR     A           ; Clear carry bit
         SBC    HL,DE      ; Subtract table value from value
         ; input
         JP     C,GONEN    ; If carry then do for next digit
         INC    A           ; Inc count (ASCII in A)
         JR     SUBBA      ; Do next subtraction
GONEN    ADD    HL,DE      ; Restore value before last
         ; subtraction
         LD     (1X+0),A    ; Store ASCII Number in memory
         INC    1X         ; Inc memory pointer
         INC    1Y         ; Point to next table value
         INC    1Y         ;
         DEC    E           ; Test if E = 0
         JR     NZ,NUMLP   ; No then try for next digit
         XOR    A           ; Clear A and place in store
         LD     (1X+0),A    ; as EOS = End of string
         POP    1Y         ; *
         POP    1X         ; *
         POP    DE         ; *   Restore all saved registers
         POP    HL         ; *   and
         POP    AF         ; *
         RET                    ; Exit

```

```
BTOAT      DEFW  10000 ; Table of subtraction constants
           DEFW  1000  ; for conversion routine
           DEFW  100   ;
           DEFW  10
           DEFW  1
```

CLEARING AND RESETTING ROUTINES

; CLRMF clears the MOTBF array

```
CLRMF    PUSH    BC           ; *
         PUSH    DE           ; * Save Registers used
         POP     HL           ; *
         LD     HL,MOTBF      ; Point to MOTBF(0)
         LD     DE,MOTBF +1   ; Point to MOTBF(1)
         LD     BC,5          ; BC = Count
         LD     (HL),0        ; MOTBF (0) = 0
         LDIR                    ; Copy through complete array
         POP     HL           ; *
         POP     DE           ; * Restore Registers used
         POP     BC           ; *
         RET                    ; Exit
```

; CTBUF clears TBUF, DRBUF and MOTBF

; Note all must be in order

```
CTBUF    PUSH    BC           ; *
         PUSH    DE           ; * Save Registers
         PUSH    HL           ; *
         LD     HL,TBUF       ; HL points to TBUF(0)
         LD     DE,TBUF + 1   ; DE points to TBUF(1)
         LD     BC,17         ; BC = Count of 17
         LD     (HL),0        ; Clear first element
         LDIR                    ; Now clear next 17 elements
         POP     HL           ; *
         POP     DE           ; * Restore Registers
         POP     BC           ; *
         RET                    ; Exit
```

SUBROUTINE GINT

; This subroutine gets a signed 16 bit integer
 ; from the TRS80 Keyboard.
 ; If a bad number istyped it returns with the
 ; Status flag - non zero.
 ; The 2's complement number is returned in HL

```

GINT      PUSH      BC      ; *
          PUSH      DE      ; * Save Registers
          XOR       A        ; Clear A and carry
          SBC      HL,HL    ; Zero HL
          LD       B,5      ; Maximum of 5 characters
          LD       (MIN),A  ; Clear MIN=Minus Flag
GINT1     CALL      GCHRA   ; Get a character and display it
          CP       SPAC     ; Is it a space?
          JR       Z,GINT1  ; Yes then skip
          CP       NL       ; Is it a newline?
          JP       Z,PRET1  ; Done if new line, return zero
          CP       MINUS    ; A minus number ?
          JR       NZ,POSON ; No then see if positive
          LD       A,1      ; Set minus flag
          LD       (MIN),A  ;
          JR       GINT2    ; Get rest of number
PCSON     CP       '+'      ; Is number a positive number
          JR       NZ,NUM1  ; See if numeric
GINT2     CALL      GCHRA   ; Get next character
NUM1      CP       NL       ; Newline?
          JR       Z,NUMET  ; Yes then exit
          ADD      HL,HL    ; Double number
          PUSH     HL       ; Save X 2
          ADD      HL,HL    ; X 4
          ADD      HL,HL    ; X 8
          POP      DE       ; Restore X 2
          ADD      HL,DE    ; Now add to get X 10
          CP       0        ;
          JR       C,ERRN2  ; If number less than ASCII 0 ERR
          CP       '9' + 1  ; If number greater than ASCII
          JR       NC,ERRN2 ; 9 then error
          SUB      NUMBA    ; Number input OK, so make into
          LD       E,A      ; Binary and
          LD       D,0      ; load into DE
          ADD      HL,DE    ; Now add to total
          DJNZ     GINT2    ; Do for next digit
          CALL     PNEWL    ; Print a new line
NUMET     LD       A,(MIN)  ; Is number negative?
          OR       A        ;
          JR       Z,PRET1  ; No then finish off
          LD       A,L      ; else complement
          CPL      ; The value in HL
          LD       L,A      ;
          LD       A,H      ; (2's Complement)
  
```

```

                CPL                ;
                LD      H,A        ;
                INC     HL         ;
PRET1          XOR     A           ; Clear A and flags
                POP     DE        ; * Restore Registers
                POP     BC        ; *
                RET              ; and return
ERRN2         CALL    PNEWL       ; Print a newline
                LD      A,1       ; Set A to 1
                OR     A           ; Clear carry flag
                SBC    HL,HL      ; Clear HL
                OR     A           ; Clear carry flag
                JR     PRET2       ; Return with ERROR CODE

```

SUBROUTINE POSDS

```
; This routine displays the POSAR array for the
; user to see how far the arm is from its
; "Home position"
```

```

POSDS      PUSH      AF          ; *
           PUSH      BC          ; *
           PUSH      DE          ; *   Save all registers
           PUSH      HL          ; *
           LD        HL,POSST    ; Print "RELPOS="
           CALL      PSTR        ; String
           LD        B,6         ; Motor count into B
           LD        DE,POSAR    ; Point to array containing offsets
NPOSA      LD        A,(DE)      ; Get lower order byte into
           LD        L,A         ; L
           INC       DE          ; Increment memory pointer
           LD        A,(DE)      ; Get higher order byte into
           LD        H,A         ; H
           INC       DE          ; Increment to next number
           LD        1X,NUMAR    ; 1X points to result string
           CALL      CBTAS       ; Convert HL and leave in (1X)
           LD        HL, NUMAR   ; Point to result string
           CALL      PSTR        ; Print it
           CALL      PSPAC       ; Print a space
           DJNZ     NPOSA       ; Do for next motor
           CALL      PNEWL       ; Print a new line, all done
           FOP       HL          ; *
           POP       DE          ; *
           POP       BC          ; *   Restore all Registers
           POP       AF          ; *
           RET                ; Now return

```

SUBROUTINE

POSIC

```
; POSIC increments the signed 2's complement 16 bit
; motor step offset counts. It does not check for overflow,
; But this is very unlikely. The base would need to
; be rotated about 30 times to cause such an event.
```

```
POSIC      PUSH    AF          ;
           PUSH    BC          ; *
           PUSH    DE          ; * Save registers
           PUSH    HL          ;
           LD      B,6         ; B = motor count
           LD      DE,MOTBF+5  ; Point to MOTBF
           LD      HL,POSAR+10; Point to POSAR (relative position)
NPOS1      PUSH    BC          ; Save motor count
           LD      C,(HL)      ; Get lower POSAR byte in C
           INC     HL          ; Point to Higher byte
           LD      B,(HL)      ; Get higher byte in B
           LD      A,(DE)      ; Get direction byte from MOTBF
           AND     3           ; Clear all higher bits from D7-D3
           OR      A           ; Is it zero?
           JR      NZ,NONZM    ; No skip
           DEC     HL          ; Yes then move POSAR pointer back
           JR      NPOS2      ; and continue with next motor
NONZM      BIT     1,A         ; Test direction bit
           JR      NZ,RDPOS    ; Do for reverse direction
           INC     BC          ; Advance element
           JR      STPCS      ; Restore 16 bit POSAR element
RDPOS      DEC     BC          ; Advance negative POSAR element
STPOS      LD      (HL),B     ; Store higher byte
           DEC     HL          ; Move pointer to lower byte
           LD      (HL),C     ; Store lower byte
NPOS2      DEC     HL          ; Back up POSAR pointer to
           DEC     HL          ; next motor position slot
           DEC     DE          ; Backup MOTBF pointer to next slot
           POP     BC          ; Restore Motor count
           DJNZ   NPOS1      ; Do next motor
           POP     HL          ;
           POP     DE          ; * Restore used Registers
           POP     BC          ;
           POP     AF          ;
           RET                ; Done, Exit
```

SUBROUTINE STORE

; STORE copies the TBUF array into the locations pointed to
 ; by CUROW. If the TBUF array is completely empty then the
 ; copy is not done. The COUNT and the CUROW variables
 ; are both updated, and a check is made to ensure that
 ; a store overflow is caught and the user told.

```

STORE      PUSH      BC          ; *
           PUSH      HL          ; * Save registers
           LD        HL,TBUF     ; Point to TBUF
           LD        B,6         ; B = motor count
STEST      LD        A,(HL)      ; Get TBUF (N)
           OR        A          ; Is TBUF element zero
           JR        NZ,STOR1    ; No then do store
           INC       HL          ; Point to next element
           DJNZ     STEST        ; Go dc next element check
           JR        EXIT        ; All TBUF zero so exit
STOR1      LD        (1X+0),0    ; Clear DRBUF element
           LD        HL,(COUNT) ; Get current count value
           INC       HL          ; Advance it
           LD        A,H         ; See if over or at 512 bytes
           CP        1          ;
           JP        NC,OVRFW    ; Yes then overflow
           LD        (COUNT),HL ; Put back advanced count
           LD        DE,(CUROW)  ; Get current row pointer in DE
           LD        HL,TBUF     ; Get TBUF pointer in HL
           LD        BC,0006     ; Count for six motors
           LDIR       ; Copy TBUF to ARST(1)
           LD        (CUROW),DE  ; Replace updated row pointer CUROW
           CALL      CTBUF       ; Clear buffers
EXIT       POP       HL          ; *
           POP       BC          ; * Restore Registers
           RET        ; Now return to caller
OVRFW     LD        HL,OVFMS     ; Print overflow situation
           CALL      PSTR        ; Message
           CALL      GCHRA       ; Get response
           CALL      PNEWL       ; Print a new line
           CP        'D'        ; User typed a 'D'
           JP        Z,REDO      ; Yes then clear all
           CP        'S'        ; User typed an 'S'
           JR        Z,EXIT2     ; Yes exit with sequence saved
           JR        OVRFM       ; Bad input, try again
REDO      CALL      INIT        ; Clear all arrays etc
EXIT2     POP       HL          ; *
           POP       BC          ; * Restore Registers
           POP       BC          ; Throw away return address
           JP        QUES1       ; Back to main loop
  
```

SUBROUTINE RESET

; This subroutine clears the POSAR array

```
RESET      PUSH      BC          ;
           PUSH      DE          ; * Save Registers
           PUSH      HI.         ; *
           LD        HL,POSAR    ; Point to POSAR start
           LD        DE,POSAR+1  ; Point to next element
           LD        (HL),00     ; Clear first POSAR element
           LD        BC,11       ; Eleven more row counts to clear
           LDIR                    ; Clear POSAR array
           LD        HL,STRST    ; Print "ARM RESET" message
           CALL     PSTR         ; and
           POP       HL          ; *
           POP       DE          ; * Restore Registers and
           POP       BC          ; *
           RET                    ; Return to caller
```

INPUT/OUTPUT ROUTINES

; PUTCHR prints a character in A

```

PUTCHR      PUSH    AF      ; Save AF
            PUSH    DE      ; Save DE
            CALL    PCHR    ; Print character in A
            POP     DE      ; Restore DE
            POP     AF      ; Restore AF
            RET     ; Done, Exit
    
```

; PSTR prints a string pointed to by HL

```

PSTR        PUSH    BC      ; * Save registers that are
            PUSH    DE      ; * corrupted by the TRS80
            CALL    PUTSTR  ; * Print the string
            POP     DE      ; * Restore Registers
            POP     BC      ;
            RET     ; Done, Exit
    
```

: PSPAC prints a space character

```

PSPAC       PUSH    AF      ; Save AF
            LD     A,20     ; A = Space character
            CALL    PUTCHR  ; Print it
            POP     AF      ; Restore AF
            RET     ; Done, Exit
    
```

; PNEWL prints a new line to the screen

```

PNEWL       PUSH    AF      ; Save AF
            LD     A,0DH    ; A = Newline character
            CALL    PUTCHR  ; Print it
            POP     AF      ; Restore AF
            RET     ; Done, Exit
    
```

: SCKBD Scans the keyboard once and returns, non
; zero if character found

```

SCKBD       PUSH    DE      ; Save DE
            CALL    KBD     ; See if character is there
            POP     DE      ; Restore
            RET     ; Done, Exit
    
```

; GCHRA gets a character from keyboard and displays it

```

GCHRA       CALL    GCHR    ; Get a character
            CALL    PUTCHR  ; Print it
            RET     ; Done, Exit
    
```

CLEAR SCREEN ROUTINE

```
; Simple scrolling type screen clear

CLRSC      PUSH      BC      ; Save used register
           LD        B,16    ; Get screen row count
UP1RW      CALL      PNEWL   ; Print a new line
           DJNZ     UP1RW   ; Do 16 times
           POP      BC      ; Restore Register
           RET          ; Exit
```

DELAY ROUTINES

```

; Delay for 10 * B + 10 M cycles
DELSW      PUSH      BC      ; Save BC
DELS1      PUSH      BC      ; Delay for 11 T state
           NOP        ; 4 T state delay
           NOP        ; 4 T state delay
           POP        BC      ; Delay for 11 T states
           DJNZ      DELS1    ; Do delay times value in B
           POP        BC      ; Restore BC
           RET        ; Exit
DELS       PUSH      BC      ; Save BC
           LD        B,20    ; Set B for 0.001 sec delay (apx)
           CALL     DELSW    ; Do delay
           POP        BC      ; Restore BC
           RET        ; Exit
DELT       PUSH      BC      ; Save BC
           LD        B,0     ; Set B for 0.01 sec delay (apx)
           CALL     DELSW    ; Do delay
           POP        BC      ; Restore BC
           RET        ; Exit
DELLN      PUSH      BC      ; Save BC
           LD        B,200   ; Set B for 1.0 sec delay (apx)
DELD       CALL     DELSW    ; Do delay
           DJNZ     DDDD     ; Do next delay section
           POP        BC      ; Restore BC
           RET        ; Exit

```

FULL STEPPING AND HALF STEPPING THE MOTORS

Two tables are shown below, the first indicates the sequence for full stepping the motors and the second table shows the pulse pattern for half stepping the motors.

FULL STEPPING SEQUENCE

QA	QB	QC	QD	<u>STEP</u>
1	0	1	0	1
1	0	0	1	2
0	1	0	1	3
0	1	1	0	4

HALF STEPPING PULSE SEQUENCE

QA	QB	QC	QD	<u>STEP</u>
1	0	1	0	1
1	0	0	0	1.5
1	0	0	1	2
0	0	0	1	2.5
0	1	0	1	3.0
0	1	0	0	3.5
0	1	1	0	4
0	0	1	0	4.5

The documented program contains a table FTABL which is shown below. This table contains the step sequence for full stepping also shown below is the new table FTABLH which contains the sequence for half stepping. To use this table (FTABLH) in the program it will be necessary to alter a few lines of code in the DRAMT routine. The comparison with 5 CPI 5 should be changed to a comparison with 9 and the program line LD A,4 should be changed to LD A,8. The table FTABL should now be changed so it appears as FTABLH

FULL STEP TABLE

FTABL	DEFB	192	Step number
	DEFB	144	1
	DEFB	48	2
	DEFB	96	3
	DEFB		4

HALF STEP TABLE

FTABLH	DEFB	192	Step number
	DEFB	128	1
	DEFB	144	1.5
	DEFB	16	2
	DEFB	48	2.5
	DEFB	32	3
	DEFB	96	3.5
	DEFB	64	4
	DEFB		4.5

A

P

P

If you compare the table values W on the previous page you will not see L is because Q8 and Q9 are not above table due to the hardware in the lines.

I

NOTE

REMEMBER WHEN WRITING PROGRAMS ON THE ARM SO THAT THE Q8 AND Q9 CANNOT BE REVERSED, SO THAT THE FOR FOUR

A

Q6 = Q8

Q7 = Q9

Q8 = Q6

Q9 = Q7

T

I

O

N

S

If you compare the table values with the tables on the previous page you will note a difference, this is because QB and QC are exchanged in the above table due to the hardware switching these two lines.

NOTE

REMEMBER WHEN WRITING PROGRAMS DIRECTLY DRIVE THE ARM SO THAT THE QB AND QC OUTPUT BITS SHOULD BE REVERSED, SO THAT THE TOP FOUR BITS ARE:-

D8 = QA
D7 = QC
D6 = QB
D5 = QD

CONSTRUCTION OF A SUITABLE PORT FOR THE ARMDROID

A circuit diagram is given which describes in particular the construction of an 8 bit bi-directional, non latched port. The circuit as given is for the TRS80 bus, but it should be possible with reasonably simple modifications to alter it for most Z80 type systems.

The circuit described is a non latched port so the output data will appear for only a short period on the 8 data lines.


As can be seen from the diagram, the circuit draws its 5 volt power supply from the arm's interface port, and not from the processor it is connected to. The port was constructed this way due to the fact that some commercial microprocessor systems do not have a 5v output supply.

When the above circuit is connected to the arm's interface card the bottom bit is usually pulled high, thus if the user inputs from the port at any time the data presented will mirror the state of the reed switches.

To output data to the arm using this port the user should send the data to the port with the bottom bit cleared. The data will then be latched through to the addressed arm motor latch.

The components for the described port should be easily available from most sources.

TRS80 8 BIT INTERFACE (NON LATCHED BI-DIRECTIONAL)



CONNECTION OF THE ARMDROID TO THE TRS80 PRINTER PORT

The TRS80 printer port can be used to drive the robot arm, but when using the printer port it will not be possible to read the reed-switches connected to the arm as this port is not a bi-directional port. The TRS80 to ARMDROID connections are shown below.

TRS80 PRINTER PORT PIN CONNECTIONS	ARMDROID CONNECTION ON INTERFACE BOARD
18	0 volts
17	D8
15	D7
13	D6
11	D5
9	D4
7	D3
5	D2
3	D1

The software driving the motors should output data to the robot arm in the following manner.

The following Z80 code sequence assumes the correct driving pattern and motor address is in the Z80 accumulator.

```
OR      0 1H    ; Set bit D1
LD      PORTAD,A; Send data to port
AND     0FEH   ; Clear bit D1
LD      PORTAD,A; Now latch data pulse to
                        ; selected motor
```

In the case of the TRS80 level 11 the printer port address is:

PORTAD equals 37E8H

CONNECTION OF ARMDROID TO PET/VIC COMPUTERS

PET/VIC USER PORT CONNECTOR

PIN NO	PET/VIC NOTATION	ARMDROID NOTATION
C	PA0	D1
D	PA1	D2
E	PA2	D3
F	PA3	D4
H	PA4	D5
J	PA5	D6
K	PA6	D7
L	PA7	D8
N	GROUND	GROUND

I/O Register Addresses (User Ports)

VIA Data Direction Control: 37138

PET Data Directional Control Register: 59459

VIC I/O Register Address: 37136

PET Data Register Address: 59471

The data direction registers in the VIA define which bits on the respective user ports are input and which are to be used as output bits. A binary one in any bit position defines an output bit position and a zero defines that bit as an input bit.

SIMPLE BASIC ARM DRIVER FOR VIA (PET/VIC)

```
5 L = 37136: Q = 37138
10 PRINT "VIC ARMDROID TEST"
20 PRINT
30 PRINT "HALF STEP VALUES"
40 T = 8: C = 2: S = 10: M = 1: I = 1: A$ = "F"
50 FOR I = 1 TO T: READ W(I): PRINT W(I): NEXT I
60 POKE Q, 255
70 INPUT "MOTOR NUMBER (1-6)"; M
80 IF M<1 OR M>8 THEN 70
90 INPUT "FORWARD BACKWARD"; A$
100 IF A$ = "F" THEN D = 0: GOTO 130
110 IF A$ = "B" THEN D = 1: GOTO 130
120 GOTO 90
130 INPUT "STEPS"; S
140 IF S<1 THEN 130
150 O = M + M + 1
160 FOR Y = 1 TO S*C
170 F = W(I) + O
180 POKE L,F
190 POKE L,F-1
200 IF D = 0 THEN 230
210 Y = Y + 1: IF Y>T THEN Y = 1
220 GOTO 240
230 Y = Y - 1: IF Y<1 THEN Y = T
240 NEXT Y
250 GOTO 70
260 DATA 192, 128, 144, 16, 48, 32, 96, 64
THE VALUES FOR L AND Q FOR THE PET ARE
Q = 59459 = DATA DIRECTION
L = 59471 = I/O
```

MOTOR STEP RELATIONSHIP PER DEGREE INCREMENT

Below are shown the calculations for each joint to enable the user to calculate the per motor step relationship to actual degree of movement.

These constants are necessary for users wishing to formulate a cartesian frame reference system or a joint related angle reference system.

Base

Motor step angle x ratio 1 x ratio 2

$$7.5 \times \frac{20 \text{ teeth}}{72 \text{ teeth}} \times \frac{12 \text{ teeth}}{108 \text{ teeth}}$$

= 0.2314 degree step or 4.32152 steps per degree.

Shoulder

$$7.5 \times \frac{14 \text{ teeth}}{72 \text{ teeth}} \times \frac{12 \text{ teeth}}{108 \text{ teeth}}$$

= 0.162 degree per step or 6.17284 steps per degree

Elbow

Same as shoulder joint

Wrists

Same as base joint calculations

Hand

$$7.5 \times \frac{20 \text{ teeth}}{72 \text{ teeth}} \times \frac{12 \text{ teeth}}{108 \text{ teeth}} = 0.231 \text{ degree per step}$$

$$\frac{\pi \times d \times 0.231}{360} = (0.0524/2)\text{mm}$$

360

=0.0262mm = hand pulley motion per step

Total hand open to close pulley movement = 20.0mm

Angletraversedbysinglefinger=50degrees

$$\frac{50^\circ}{20.0 \text{ mm}} \times 0.0262\text{mm}$$

= 0.0655 degrees per step or 15.2672 steps per degree

$\pi = 3.1415926$

$d = 26\text{mm} = \text{pulley diameter}$

SOME OVERALL DIMENSIONS

Shoulder pivot to pivot = 190mm
Forearm pivot to pivot = 190mm
Finger wrist pivot to fingers closed = 90mm
 wrist pivot to finger open (90) = 99mm

Bottom of base to shoulder pivot = 238mm


ANGULAR JOINT SPANS

Shoulder up = 153 ,down 45
Forearm up = 45 ,down 150
Wrist up = 100 ,down 100
Base no limit ,but suggest caution not to
 overwind cables in base
Hand fingers move over 50

(All above measurements are in degrees)

NOTE

The above measurements were taken with the arm joints held in a horizontal plane:




SOME EXTRA POINTS TO BEAR IN MIND

- a) Long Lead of LED goes to NEGATIVE
Short lead of LED goes via 4.7 kohm Resistor
to POSITIVE
- b) Due to LED hole being slightly too large a grommet
will first have to be fitted to the LED and its holder
can then be super glued if necessary into the grommet.
- c) The Torque available is largely a function of speed
and hence the user can expect performance to deteriorate
as speed is increased. Tables are supplied earlier
in the manual.

FINAL NOTE

BEST WISHES AND GOOD LUCK

A handwritten signature in black ink, appearing to read "J. Reki". The signature is written in a cursive style with a large initial "J" and a long, sweeping underline.